

# MACHINE TOOL ENGINEERING

[A Textbook for Engineering Students]

621-9  
NAG

ACC. NO.	002723
CLASS. NO.	621.9 NAG

**G.R. NAGPAL**


*B.Sc., B.Sc. Engineering (Mechanical)*

*M. Tech. (Mechanical)*

*Lecturer Mech. Engineering Department*

*Y.M.C.A. Institute of Engineering*

*Faridabad (Haryana)*



**KHANNA PUBLISHERS**

2-B, NATH MARKET, NAI SARAK  
DELHI-110006

Phones : 2912380 ; 7224179

02723

Verification	
2017	
2019	

*Published by :*

Romesh Chander Khanna  
for KHANNA PUBLISHERS  
2-B, Nath Market, Nai Sarak  
Delhi-110006

All Rights Reserved

[This book or part thereof cannot be translated or reproduced in any form (except for review or criticism) without the written permission of the Author and the Publishers.]

*First Edition* : 1984  
*Seventh Edition* : 1996, October  
*1st Reprint* : 1997 October

*Price* : Rs. 65.00

*Typesetted at* : Goswami Printers, Street No. 2, Brahmpuri, Delhi-110053  
*Phone* : 226 31 17

*Printed at* Bharat Offset, Delhi-6, Ph.: (011)3284486

## Preface

The author is glad to present this book in a new revised format. This thoroughly revised edition is outcome of various suggestions and comments received from readers and professors of various universities from all over India for which I am really thankful for their suggestions and comments. I think this book will be now more useful for the students of Degree, Diploma and other similar courses. The purpose of this book is to provide a comprehensive knowledge of various aspects of the following :

- (i) Method of metal cutting
- (ii) Cutting tools
- (iii) Machine tools.

Every effort has been made to present the subject matter in a simple language. The study and recitation is given in to develop the applications of the principles studied. Numerous examples and problems have been included, followed by a separate chapter on objective type questions to make topics more clear and prepare students for any type of examination.

Suggestions for improvement of the book shall be gratefully received and appreciated.

The author is thankful to the Publisher for the most painstaking and co-operative attitude for bringing out this book in a very short period.

G.R. NAGPAL

**By the same Author :**

- (i) Power Plant Engineering
- (ii) Machine Drawing
- (iii) Machine Design
- (iv) Material Science
- (v) Geometrical Drawing
- (vi) Tool Engineering and Design



## Contents

Chapter	Pages
<b>Introduction</b>	<b>i—ii</b>
<b>1. Process of Metal Cutting</b>	<b>1—73</b>
1.0. Metal Cutting	1
1.1. Chip Removal Processes	1
1.2. Chipless Processes	2
1.3. Metal Cutting Principle	2
1.3.1. Basic Elements of Machining	4
1.4. Classification of Cutting Tools	4
1.5. Tool Geometry	4
1.5.1. Methods of holding tool	11
1.6. Tool Signature	12
1.6.1. Requirements of a cutting tool	12
1.7. Two Systems of Defining the Cutting Angles of a Single Point Tool	13
1.8. Types of Metal Cutting Process	15
1.8.1. Comparison of orthogonal and oblique cutting	17
1.9. Chip Formation	17
1.9.1. Areas in Metal Cutting	19
1.10. Chip Thickness Ratio	20
1.11. Chip Breaker	21
1.12. Radius of Chip Curvature	23
1.13. Chip Reduction Coefficient	25
1.14. Cutting Speed, Feed and Depth of Cut	27
1.15. Objectives of a Good Tool Design	30
1.16. Cutting Tools Materials	30
1.17. Variation of Hardness with Temperature	35
1.18. Economic Comparison of Tool Materials	35
1.19. Multi-edge Cutting Tools	35
1.20. The Twist Drill	36
1.21. Elements of a Twist Drill	37
1.22. Cutting Fluids for Drilling	39
1.23. Twist Drill Grinding	39
1.23.1. Twist drill failure	41
1.24. Rake and Relief Angles of a Twist Drill	41
1.25. Drill Specifications	42



Chapter	Pages
1.26. Cutting Speed, Feed and Depth of Cut	42
1.27. Machining Time	44
1.28. Forces Acting on a Drill	45
1.29. Power of Drilling	46
1.30. Milling Cutters	46
1.31. Elements of a Plain Milling Cutters	48
1.32. Milling Cutter Sharpening	50
1.33. Material for Milling Cutters	50
1.34. Number of Teeth in a Cutter	51
1.35. Cutting Speed and Feed for Milling Cutter	52
1.36. Power Required at the Cutter	53
1.37. Machining Time	54
1.37.1. Broaching Tool	56
1.38. Improving Cutting Efficiency	57
1.39. Power Distribution	57
140. To Determine Power Rating of Electric Motor	57
1.41. Cutting Tool Design	58
1.42. Friction between Chip and Tool	58
1.43. Friction in Metal Cutting	58
<b>2. Mechanics of Metal Cutting</b>	<b>71—110</b>
2.1. Cutting Forces in Orthogonal Cutting	71
2.2. Stress and Strain in the Chip	76
2.3. Shear Strain	77
2.4. Work Done and Power Required	79
2.5. Power Consumed in Metal Cutting	79
2.6. Machine Tool Efficiency	81
2.7. Metal Removal Rate ( $w$ )	81
2.8. Ernst-Merchant Theory	81
2.9. Lee and Shaffer's Theory	82
2.10. Velocities in Metal Cutting	82
2.10.1. Velocity Relationship	83
2.10.2. To prove $V_c = rV$	84
2.10.3. Effect of cutting variables on cutting forces	84
2.11. Improvement of Cutting Efficiency	85
2.12. Requirements Made to the Cutting Tool	85
2.13. Cutting Tool Design	85
2.14. Dynamometry	85
2.15. Types of Dynamometers	86
2.16. Force Measurement	86

Chapter	Pages
<b>3. Machinability</b>	<b>111—145</b>
3.1. Machinability	111
3.2. Machinability Index	112
3.2.1. Effect of Micro Structure on Machining	112
3.3. Basic Objectives of Economical Machining	113
3.4. Tool Failure	113
3.4.1. Temperature Failure	114
3.5. Tool Life	117
3.6. Relationship between the Cutting Speed and Tool Life	118
3.7. Effect of Feed and Depth of Cut on Tool Life	120
3.7 (a). Tool Life in Terms of Metal Removed	121
3.8. Effect of Type of Cutting	121
3.9. Effect of Tool Material	121
3.10. Effect of Tool Geometry on Tool Life	122
3.11. Effect of Work-piece Material	123
3.12. Effect of Cutting Fluid	123
3.13. Tool Grinding	123
3.14. Cost Analysis	124
3.14.1. Treatment of Tool	124
3.15. Cost per Component	124
3.16. Objectives of Machining	126
3.17. Choice of Cutting Speed	126
3.18. Trends in Conventional Machining (Metal Cutting)	128
<b>4. Cutting Fluids</b>	<b>146—164</b>
4.1. Cutting Fluids	146
4.2. Sources of Heat in Metal Cutting	146
4.3. Thermal Aspects of Metal Machining	146
4.3.1. Temperature in the Primary Deformation Zone	147
4.3.2. Heat Distribution in Metal Cutting	148
4.3.3. Temperatures in the Secondary Deformation Zone	148
4.4. Functions of Cutting Fluid	148
4.5. Properties of Cutting Fluid	150
4.6. Types of Cutting Fluids	150
4.7. Lubricants	152
4.8. Selection of a Cutting Fluid	153
4.9. Cutting Fluid Penetration	154
4.10. Application of Cutting Fluid	155

Chapter	Pages
4.11. Effect of Cutting Fluid on Cutting Speed and Tool Life ...	156
4.12. Maintenance of Cutting Fluid ...	158
4.13. Characteristics of a Lubricant ...	158
4.14. Tool Friction ...	159
4.15. Effect of Cutting Fluid on Chip Concentration ...	159
4.16. Benefits Achieved with the Use of Cutting Fluids ...	159
4.17. How Coefficient of Friction is Reduced ...	160
<b>5. Surface Finishing Processes</b>	<b>165—195</b>
5.1. Surface Finish ...	165
5.1.1. Grinding ...	165
5.2. Abrasive Materials ...	166
5.2.1. Abrasive Grain Size ...	167
5.2.2. Bonds ...	168
5.2.3. Grade ...	169
5.2.4. Structure ...	170
5.2.5. Marking System of Grinding Wheels ...	170
5.3. Grinding Wheel Cutting Action ...	171
5.4. Grinding Wheel Selection ...	172
5.5. Shapes of Grinding Wheels ...	173
5.5.1. Mounted Wheels and Points ...	174
5.6. Types of Grinding Machines and Processes ...	174
5.6.1. Cylindrical grinders ...	175
5.7. Depth of Cut ...	177
5.8. Feed ...	177
5.9. Cutting Speed ...	177
5.10. Machining Time ...	178
5.11. Surface Grinders ...	178
5.12. Tool and Cutter Grinder ...	179
5.13. Centreless Grinding ...	180
5.14. Mounting of Grinding Wheel ...	182
5.15. Dressing and Truing ...	182
5.16. Grinding Wheel Balancing ...	183
5.17. Operating Speeds and Feeds ...	184
5.18. Theory of Grinding ...	184
5.19. Grinding Wheel Wear ...	184
5.19.1. Grinding Ratio ...	187
5.20. Grinding Temperature ...	187
5.21. Power Required for Grinding ...	188
5.22. Polishing ...	190

Chapter	Pages
5.23. Buffing ...	190
5.24. Lapping ...	190
5.25. Honing ...	192
5.26. Super Finishing ...	193
5.27. Specific Energy for Grinding ...	194
<b>6. Chatter and Surface Finish</b>	<b>196—211</b>
6.1. Chatter and Vibrations in Machining ...	196
6.1.1. Vibrations in Machine tool ...	197
6.2. Types of Vibrations ...	197
6.3. Factors Affecting Chatter ...	198
6.4. Types of Vibratory Systems ...	199
6.5. Elimination of Chatter ...	200
6.6. Vibration Isolation ...	200
6.6.1. Vibration measurement in machine tools ...	202
6.6.2. Effects of vibrations ...	202
6.7. Surface Finish ...	203
6.8. Factors Affecting Surface Finish ...	203
6.9. Surface Finish Terminology ...	205
6.10. Idle Surface Roughness ...	207
6.11. Measurement of Surface Roughness ...	208
6.12. Surface Finish Representation ...	209
6.13. Units of Surface Roughness ...	210
<b>7. Basic Features and Kinematic Requirements of Machine Tools</b>	<b>212—257</b>
7.1. Machine Tool ...	212
7.1.1. Characteristics of machine tool ...	213
7.1.2. Objectives of machine tool ...	214
7.1.3. Production capacity ...	215
7.1.4. Stiffness and rigidity of machine tools ...	215
7.1.5. Precision ...	216
7.1.6. Productive time ...	216
7.2. Classification of Machine Tools ...	216
7.3. Control Systems of Machine Tools ...	217
7.4. Safety and Convenience of Machine Tool Controls ...	218
7.5. Cutting Motion in Machine Tool ...	218
7.6. Forces in Machine Tool ...	221
7.7. Process Capability of a Machine Tool ...	222
7.7.1. Compliance of machine tool ...	222
7.8. Essential Requirements of a Machine Tool ...	224
7.9. Selection of Machine Tool ...	225

Chapter	Pages
7.10. General Requirements of Machine Tool Design ...	225
7.11. Basic Features of a Machine Tool ...	225
7.12. Bed, Structure or Frame ...	226
7.13. Procedure to Design a Machine Tool Structure ...	229
7.13.1. Use of reinforcing ribs or stiffness in lathe beds ...	229
7.13.2. Forces to be considered for machine tool structures design ...	230
7.14. Sides and Slide Ways (Guide Ways) ...	231
7.14.1. Classification of Guide ways ...	234
7.14.2. Slide ways working conditions ...	235
7.14.3. Oil for slide ways ...	235
7.14.4. Friction in slide ways ...	236
7.14.5. Accurate positioning of slide ways ...	236
7.14.6. Classification of rolling guides ...	237
7.15. Requirements of Guide Ways ...	237
7.15.1. Design criteria for slide ways ...	238
7.15.2. Machine tool columns ...	238
7.16. Materials of Beds and Guides ...	239
7.17. Wear Resistance of Guides ...	240
7.18. Life of Guide Ways ...	241
7.18 (a). Working Life of Rolling Guides ...	241
7.18 (b). Friction in Rolling Guides ...	242
7.18 (c). Methods of improving functions of slide ways ...	243
7.18.1. Basic principles of design for rigidity ...	243
7.18.2. Basic principles of design for strength ...	244
7.18.3. Static and dynamic stiffness ...	245
7.18.4. Basic design procedure of machine tool structures ...	245
7.19. Spindles and Bearings ...	245
7.20. Materials of Spindles ...	247
7.21. Lubrication of Bearings ...	247
7.22. Selection of Bearings ...	248
7.23. Types of Bearings ...	248
7.24. Rolling Bearings ...	248
7.25. Plain Bearings ...	249
7.25.1. Comparison of plain and rolling bearings ...	250
7.26. Hydrostatic (externally pressurised) Bearings ...	250
7.27. Bearing Metals ...	251
7.28. Power Units ...	251

Chapter	Pages
7.29. Transmission Element ...	251
7.30. Work Holding and Tool Holding Elements ...	252
7.31. Kinematics in Machine Tools ...	252
7.32. Geometric Forms of Engineering Components ...	252
7.33. Methods of Production of Surfaces ...	253
7.34. Comparison of Forming and Generating ...	255
7.35. Degrees of Freedom ...	255
7.36. Trends in the Development of Modern Machine Tools ...	256
2.36.1. General requirements of Maching Tool Design ...	257
7.37. Maintenance of Machine Tool ...	258
7.38. Machine Tool Efficiency ...	258
<b>8. Kinematic Drives of Machine Tools</b> ...	<b>262—314</b>
8.1. Drive ...	262
8.1.1. Individual drive and group drive ...	263
8.1.2. Electric Motors for machine tool drives ...	263
8.2. Strength and Power of Machine Tools ...	265
8.3. Machine Tool Spindle Speeds ...	266
8.4. Ray Diagram ...	269
8.5. Speed Spectrum ...	269
8.6. Standard Values of Common Ratio ...	270
8.7. Number of Spindle Speed Steps ...	271
8.8. Principle Kinematic Relationship in the Spindle Drive ...	272
8.9. Number of Spindle Speed Steps ...	272
8.10. Range Ratio of Speed Variation in a Drive ...	273
8.11. Limiting Transmission Ratios ...	273
8.12. Speed Structure Diagram ...	274
8.13. Basic Rules for layout of Gear Boxes having Sliding Clusters ...	276
8.14. Shaft Size Calculation ...	279
8.15. To Determine Module for Gears ...	280
8.16. Kinematic Functions of Machine Tools ...	281
8.16.1. To determine number of teeth on gears ...	281
8.17. Method of Obtaining Different Speeds of Spindle ...	290
8.18. Cone Pulley Arrangement ...	291
8.19. Cone Pulley Drive by Back Gears ...	291
8.20. Speed Gear Boxes ...	291
8.21. Gear Box Layout ...	292
8.22. Screw Cutting on Lathe by Using Change Gears ...	292

<i>Chapter</i>	<i>Pages</i>
8.23. Methods for Changing Speed in Gear Boxes ...	293
8.24. Sliding Gears Arrangement ...	293
8.25. Sliding Key Mechanism ...	294
8.26. Feed Gear Boxes ...	295
8.27. Norton Gear Box ...	296
8.28. Feed Gear Box of Meander Type ...	296
8.29. Clutched System ...	297
8.30. Ruppert Drive ...	297
8.31. Feed Drive of a Lathe ...	298
8.32. Pre-optive Gear Box ...	298
8.33. Infinitely Variable Drives ...	299
8.34. Types of Infinitely Variable Drives ...	299
8.35. Mechanical Stepless Drives ...	299
8.35.1. P.I.V. Drive ...	300
8.36. Electric Stepless Drives ...	301
8.37. Hydraulic Drives ...	301
8.38. Hydraulic Fluids Used in Machine Tool Drives ...	302
8.39. Element of a Hydraulic System ...	302
8.40. Pump Operation Methods ...	303
8.41. Hydraulic Valves ...	304
8.42. Hydraulic Circuits ...	304
8.43. Selection of Drive ...	305
8.44. Hydraulic Drive for Shaper and Milling Machine ...	305
8.45. Hydraulic Valves ...	305
8.46. Clutches ...	306
8.47. Control Systems in Machine Tools ...	307
8.48. Gear boxes with clutched drives ...	308
8.49. Flow chart for gear box ...	312
<b>9. Newer Machining Processes</b> ...	<b>315—330</b>
9.0. Introduction ...	315
9.1. Classification ...	315
9.2. Electrochemical Machining (E.C.M.) ...	316
9.3. Electrochemical Grinding (E.C.G.) ...	318
9.4. Electrodischarge Machining (E.D.M.) ...	319
9.5. Ultrasonic Machining (U.S.M.) ...	320
9.6. Abrasive Jet Machining (A.J.M.) ...	321
9.7. Electron Beam Machining (E.B.M.) ...	322
9.8. Laser Beam Machining (L.B.M.) ...	323
9.9. Plasma Arc Machining (P.A.M.) ...	324
9.10. Hot Machining ...	325

<i>Chapter</i>	<i>Pages</i>
9.11. Explosive Forming ...	326
9.12. Electro Magnetic Forming (E.M.F.) ...	327
9.13. Hydro Forming ...	328
9.14. Spark Erosion ...	329
<b>10. Capstan, Turret and Automatic Lathes</b> ...	<b>331—399</b>
10.0. Introduction ...	331
10.1. Comparison of Turret Lathe, Capstan Lathe and Engine Lathe ...	331
10.2. Difference Between Capstan and Turret Lathe ...	331
10.3. Principal Parts of a Capstan and Turret Lathes ...	331
10.3.1. Working and Auxiliary Motions ...	333
10.4. Production Time ...	334
10.5. Turret Indexing Mechanism ...	334
10.6. Work Holding Devices ...	335
10.7. Bar Feeding Mechanism ...	336
10.8. Economics of Turret Lathe ...	337
10.9. Turret Lathe Tooling ...	339
10.10. Vertical Turret Lathe ...	341
10.10.1. Automation ...	341
10.11. Automatic Machines ...	342
10.12. Operating Cycle of Automatic Machine Tools ...	343
10.12.1. Types of automatic machines ...	343
10.13. Automatic Cutting off Machine ...	343
10.14. Swiss Type Automatic Screw Machine ...	344
10.15. Turret Type Automatic Screw Machine ...	345
10.16. Multi-spindle Screw Machines ...	346
10.16.1. Economics of automatic machines ...	346
10.16.2. Tool slides of automatic machine tools ...	347
10.16.3. Methods of increasing production capacity ...	348
10.17. Cams ...	348
10.18. Layout of Cams ...	349
10.19. Numerical Control of Machine Tools ...	349
10.20. Basic Components of an N.C. System ...	350
10.20.1. The Numerical Control (N.C.) Procedure ...	351
10.21. Numerical Control (NC) Systems ...	353
10.21.1. N.C. System for Turning ...	354
10.21.2. Servo motor ...	354
10.22. Digital and Analogue Control ...	355
10.22.1. Axis Selection ...	355
10.22.2. XYZ Codes ...	356

Chapter	Pages
10.23. Point to Point or Positioning System ...	356
10.24. Continuous Path System or Contouring System ...	356
10.24.1. Part programming (P.P.) ...	357
10.24.2. Data required for part programming ...	358
10.24.3. Input media ...	358
10.25. Tapes ...	358
10.25.1. Punched tape readers ...	360
10.25.1. (a) Buffer Storage ...	361
10.26. Advantages and Disadvantages of Numerical Control ...	361
10.27. Codes ...	362
10.28. Machine Control Unit (MCU) ...	363
10.28.1. Features of modern N.C. machines ...	363
10.28.2. Tool designing for N.C. machines ...	364
10.28.3. Automatic Tool Changer (ATC) ...	364
10.29. Development of NC and CNC ...	364
10.30. Computer Numerical Control (CNC) of Machine Tools ...	365
10.31. Functions of CNC System ...	366
10.32. Functions of CNC ...	366
10.32.1. Recirculating Ball Screw and Nut ...	366
10.33. Advantages of CNC ...	367
10.34. Direct Numerical Control (DNC) ...	368
10.35. Major groups of N.C. Machine Tools ...	369
10.35.1. Machining Centre ...	369
10.35.2. Block and Works in N.C. Systems ...	369
10.35.3. Function Words ...	370
10.35.4. Programming Formats ...	373
10.36. CAM ...	375
10.37. Transfer machines ...	375
10.38. Advantages and Disadvantages ...	376
10.39. Economic Comparison of Various Manufacturing Systems ...	377
10.39.1. Time Comparison of Conventional CNC and FMS Machining Methods ...	377
10.40. Production Capacity of Automatic Machine Tools ...	378
10.41. Computer Application in Production ...	379
10.42. N.C. System for Simple Turning ...	380
10.43. N.C. Machine Tools Drives ...	388
10.44. Economics of Numerically Controlled Machines ...	388
10.44.1. The Coordinate System in N.C. System ...	390

Chapter	Pages
10.44.2. Coordinates and reference points in N.C. Machine Tools ...	391
10.45. Lanen Machining for Productivity ...	392
10.46. Decimal to binary conversion ...	393
<b>11. Testing, Maintenance and Erection of Machine Tools</b> ...	<b>400—410</b>
11.1. Testing of Machine Tools ...	400
11.1.1. Procedure for acceptance test ...	401
11.2. Testing Equipment ...	402
11.3. Order of Test ...	403
11.4. Test Chart for General Purpose Parallel Lathes ...	403
11.5. Maintenance of Machine Tools ...	403
11.6. Preventive Maintenance ...	407
11.7. Corrective Maintenance ...	407
11.8. Reconditioning ...	409
11.9. Erection of Machine Tools ...	409
11.10. Foundation ...	410
<b>12. Typical Problems</b> ...	<b>411—449</b>
12.1. Measurement of Tool-chip Inter-face Temperature ...	411
12.2. Measurement of Cutting Forces ...	411
12.3. Design of a Single Point Lathe Tool ...	412
12.4. Hydraulic Drive for Shaper ...	414
12.5. Quality and Performance of a Machine Tool ...	415
12.6. General Inspection of Machine Tools ...	416
12.6.1. Care and maintenance of machine tools ...	416
12.7. Lubrication Record Card ...	417
12.8. Corrective Maintenance Record Card ...	417
12.9. Geneva Wheel Mechanism ...	418
12.10. High Speed Steel (H.S.S.) Tools Bits ...	418
12.10.1. Specifying a single point tool ...	419
12.11. Valves Used in Hydraulic Systems ...	419
12.12. Copying Systems for Machine Tools ...	420
12.13. Types of Tool Bits ...	421
12.14. Hydraulic Drive for Milling Machine ...	422
12.15. Slotted Arm Quick Return Mechanism ...	423
12.16. Fellow's Gear Shaper ...	425
12.17. Care and Maintenance of Cutting Tools ...	429
12.18. Effect of Various Factors on the Axial Thrust and Torque in Drilling ...	429



Chapter	Pages
12.19. Surface Treatment of Tools	430
12.20. Preventive Maintenance Planning	431
12.21. Programme of Preventive Maintenance	431
12.22. Preventive Maintenance Repair Cycle	433
12.23. Man Power Planning	434
12.24. Preventive Maintenance Stages for Metal Cutting Equipment	435
12.25. Machine Stoppage During Preventive Maintenance	436
12.26. When to Replace a Machine Tool	436
12.27. Control Systems for Machine Tools	437
12.28. Transfer Devices in Automatic Machine Tool Systems	438
Problems	449
<b>13. Objective Type Problems</b>	<b>450—472</b>

## Process of Metal Cutting

### 1.0. Metal Cutting

Metal cutting process consists in removing a layer of metal from blank to obtain a machine part of the required shape and dimensions and with the specified quality of surface finish.

A metal cutting tool is the part of a metal cutting machine tool that, in the cutting process, acts directly on the blank from which the finished part is to be made. The metal cutting process accompanied by deformation in compression, tension and shear by a great deal of friction and heat generation is governed by definite laws. In order to cut the material from blank the cutting tool should be harder than material to be cut, the tool should penetrate the blank and the tool should be strong enough to withstand the forces developed in cutting.

Metals are given different usable forms by various processes. These processes are of two types.

(a) Chip removal processes.

(b) Non-chip removal processes (Chipless processes).

#### 1.1. Chip Removal Processes

In chip removal processes the desired shape and dimensions are obtained by separating a layer from the parent workpiece in the form of chips. The various chip forming processes are as follows :

- |                 |               |
|-----------------|---------------|
| (i) Turning     | (ii) Shaping  |
| (iii) Boring    | (iv) Drilling |
| (v) Milling     | (vi) Honing   |
| (vii) Grinding. |               |

During the process of metal cutting there is a relative motion between the workpiece and cutting tool. Such a relative motion is produced by a combination of rotary and translatory movements either of the workpiece or of cutting tool or of both. This relative motion depends upon the type of metal cutting operation. Table 1.0 indicates the nature of relative motion for various continuous cutting operations.

Table 1.0

Operation	Motion of Workpiece	Motion of Cutting Tool
Shaping	Fixed	Translatory
Turning	Rotary	Translatory
Drilling	Fixed	Rotary as well as translatory
Milling	Translatory	Rotary

In any metal cutting process the following aims should be achieved.

- (i) Work piece surface finish should be of desired quality.
- (ii) Metal removal rate should be high.
- (iii) Power consumed during the process should be low.
- (iv) Cutting tool life should be more.

### 1.2. Chipless Processes

In chipless processes the metal is given the desired shape without removing any material from the parent workpiece. Some of the chipless processes are as follows :

- (i) Rolling
- (ii) Forging
- (iii) Spinning
- (iv) Stamping.

### 1.3. Metal Cutting Principle

Metal cutting is one of the most important processes carried out in an industry. The purpose of any metal cutting operation commonly called machining is to produce a desired, shape, size and finish of a component by removing the excess metal in the form of chips from a rough block of material. Consequently the primary objective in metal cutting is the production of chips, although these chips are only a means to an end and are discarded. They may constitute more than 50% of the initial workpiece material. The machining process should be carried at high speeds and feeds and least cutting effort and at lowest cost. The cutting operation whether being carried out on lathe, milling machine or any other machine tool is based on theory which is same for all processes. Number of inter-related factors affect metal cutting, the more important factors being as follows :

- (i) The properties of work material.
- (ii) The properties and geometry of the cutting tool.
- (iii) The interaction between the tool and the work during metal cutting.

The exact mechanism of metal cutting briefly stated is that a cutting tool exerts a compressive force on the workpiece. Under this compressive force the material of the workpiece is stressed beyond its yield point causing the material to deform plastically and shear off. The plastic flow takes place in a localised region called shear plane (Fig. 1.1) which extends from the cutting obliquely up to the uncut surface ahead of tool (Fig. 1.2). The sheared material




Fig. 1.1




Fig. 1.2

begins to flow along the cutting tool face in the form of small pieces called chips. The compressive force applied to form the chips is called cutting force. The flowing chips cause wear of cutting tool. Heat is produced during shearing action. The heat generated raises the temperature of the work, cutting tool and chips. The temperature rise in the cutting tool tends to soften it and causes loss of keenness in the cutting edge leading to its failure. The cutting force, heat and abrasive wear are thus the basic features of the material cutting process.

During cutting process the following properties of the workpiece material are quite important.

- (i) Hardness
- (ii) Toughness
- (iii) Inherent hard spots and surface inclusions
- (iv) Abrasive qualities
- (v) Tendency to weld.

On the other hand the tool material should be hard, strong, tough and wear resistant.

One of the basic requirements for metal cutting operations is that the tool is harder than the work piece. Both are held rigidly and the tool tends to

penetrate into the work piece and this is how a small portion of work piece material is removed called as chip.

### 1.3.1. Basic elements of machining

The basic elements of all machining operations are as follows :

- (i) Workpiece
- (ii) Cutting tool
- (iii) Chip.

The workpiece provides the parent metal from which the unwanted material is removed by the cutting action of tool to obtain desired size and shape. For providing the cutting action a relative motion between tool and workpiece is necessary.

### 1.4. Classification of Cutting Tools

Depending upon the number of cutting edges the cutting tools used in metal cutting are classified as follows :

- (i) Single point cutting tool
- (ii) Multipoint cutting tool.

(i) **Single point cutting tool.** This type of tool has an effective cutting edge and removes excess material from the workpiece along the cutting edge. Single point cutting tool is of the following types :

- (a) Ground type
- (b) Forged type
- (c) Tipped type
- (d) Bit type.

In ground type the cutting edge is formed by grinding the end of a piece of tool steel stock. Whereas in forged type the cutting edge is formed by rough forging before hardening and grinding. In tipped type cutting tool the cutting edge is in the form of a small tip made of high grade material which is welded to a shank made up of lower grade material. In bit type, a high grade material of a square, rectangular or some other shape is held mechanically in a tool holder. Single point tools are commonly used in lathes, shapers, planers, boring machines and slotters.

Single point cutting tool may be left handed or right handed type. A tool is said to be right/left hand type if the cutting edge is on the right or left side when viewing tool from the point end. Lathe tools, shaper tools, planer tools and boring tools are single point tools.

**Multipoints cutting tools.** They have more than one effective cutting edge to remove the excess material from the workpiece. Milling cutters, drills, reamers broaches and grinding wheels are multipoint cutting tools.

### 1.5. Tool Geometry

The desirability of getting the maximum use from a tool before it needs regrinding is one of the objectives of tool technology. Tool life is defined as the length of time, a tool will operate before its failure occurs. There are many factors that contribute to cutting tool efficiency. Among the most important of these are the following :

- (i) The shape of the cutting edge that removes the excess material.
- (ii) The correct selection of the type of cutting tool for the material to be machined.
- (iii) The correct choice of cutting speed and feed.
- (iv) The proper setting of cutting tool relative to work.
- (v) The correct choice and proper application of coolants.

Unless the cutting tools is ground to the correct shape with correct angles and unless it is ground with a keen, smooth cutting edge, time will be wasted, accuracy will be impossible and a poor finish will result.

The optimum tool geometry depends upon the following factors :

- (i) Workpiece material
- (ii) Machining variables
  - (a) Cutting speed
  - (b) Feed
  - (c) Depth of cut
- (iii) Material of the tool point
- (iv) Type of cutting.

Tool geometry refers to the tool angles, shape of the tool face and the form of the cutting edges.

Fig. 1.3 shows a typical single point tool. The most important features are the cutting edges and adjacent surfaces.




Fig. 1.3

Fig. 1.4 shows the principal plane and cutting plane with reference to a single point cutting tool with respect to velocity taken along Z axis whereas Fig. 1.5 shows principal and cutting planes in relation to working surface.




Fig. 1.4




Fig. 1.5

Fig. 1.6 shows the geometry of a single point tool.

### 1.5.1. Terms and definitions

- (i) **Face.** The face is the surface over which the chip flows.
- (ii) **Cutting edge.** The cutting edge carries out the cutting.
- (iii) **Nose.** The nose is the corner, arc or chamfer at the junction of the major and minor cutting edges.
- (iv) **Flank.** Flank of the tool is the surface below the cutting edge.
- (v) **Tool angles.** The various angles influence tool performance to a considerable extent and therefore their value should be selected with great care and consideration.




Fig. 1.6

The various functions of the rake or slope of the tool face are as follows :

- (i) It allows the chip to flow in a convenient direction.
- (ii) It gives sharpness to the cutting edge.
- (iii) It increases tool life.
- (iv) An improved surface finish is obtained.

(v) The cutting force required to shear the metal is reduced, and therefore power required during cutting is reduced.

The amount of rake angle to be provided on a cutting tool depends upon the following factors :

- (i) Material of the workpiece
- (ii) Material of cutting tool
- (iii) Rigidity of the machine tool
- (iv) Depth of cut.

**Back rake angle.** It measures the downward slope of the top surface of the tool from the nose to the rear along the longitudinal axis. Its purpose is to guide the direction of the chip flow. It also serves to protect the point of the cutting tool. (Fig. 1.7). The size of the angle depends upon the material to be machined, the softer the material the greater should be positive rake angle.




Fig. 1.7

Aluminium requires more back rake angle than cast iron or steel. Back rake angle may be positive, neutral or negative. Fig. 1.8 shows a tool with a positive back rake angle. Fig. 1.9 shows a tool with a neutral back rake angle and Fig. 1.10 shows a tool with a negative back rake angle.




Fig. 1.8

Higher value of rake angle weakens the cutting edge. A negative rake angle increases tool forces to some extent but this minor disadvantage is offset by the added support to the cutting edge. This is particularly important in making intermittent cuts and in absorbing the impact during the initial engagement of the tool and work.




Fig. 1.9




Fig. 1.10

The inherently tough H.S.S. tools are used with positive rake mainly for reducing the magnitude of cutting forces power, consumption and cutting temperature.

Positive rakes are used when cutting low tensile strength and non-ferrous materials, materials which work harden while being machined.

Negative rake angles are used for machining high tensile strength materials, heavy feeds and interrupted cuts. It is the rare case that a negative rake will be used that high speed or cast tool bits. They are generally used for carbide tool cutting materials such as grey, malleable cast iron, cast steels, hot work die steels, and tool steels.

Excessive positive rake weakens the cutting edge.

Cemented carbide cutting tools are normally given negative rake because cemented carbide possess very high compressive strength and comparatively very low tensile and shear strength.

The advantages of negative rake cutting when using sintered carbide or ceramics tool under suitable conditions are as follows :

- (i) Higher cutting speeds may be used.
- (ii) There is a less tendency for a built up edge to form on the tool.
- (iii) The heat conductivity of the working part of the tool is improved.
- (iv) Favourable combination of conditions in that at high cutting speeds and corresponding high chip velocity, heat is carried away rapidly by the chip. Negative rake cutting with sintered carbide cutting tools can be applied with advantage on ductile steels. The machine tools using such tools must possess considerable rigidity and be equipped with high quality bearing.
- (v) The main cutting force is directed towards strongest part of the tool.

A cutting tool with positive rake (Fig. 1.11) results in a force component in the direction of arrow A which tends to shear the edge of tool. When




Fig. 1.11




Fig. 1.12

the cutting tool is provided with a negative rake (Fig. 1.12), the main force component is directed at the strongest rake section of the tool, as shown by arrow B. Cutting tools with negative rake angle are stronger and are used to cut high strength alloys.

However the use of an increased negative rake angle leads to increased cutting force during machining. This causes vibrations, reduces machining accuracy and raises power consumed in cutting. Therefore tools with negative rake should be used only when absolutely necessary.

**Side rake angle.** It measures the slope of the top surface of the tool to the side in a direction perpendicular to the longitudinal axis. It also guides the direction of the chip away from the job. The amount that a chip is bent depends upon this angle. With increase in side rake angle, the amount of chip has to bend decreases and hence the power required to part and bend the chip

decreases. Larger side rake angle produces smooth surface finish. Fig. 1.13 shows side rake angle.




Fig. 1.13

**End cutting edge angle.** It is the angle between the face of the tool and a plane perpendicular to the side of the shank. It acts as a relief angle that it allows only small section of the end cutting edge to contact the machined surface and prevents chatter and vibration. Normally it varies from 5 to 15°.

**Side cutting edge angle.** It is the angle between the side cutting edge and the longitudinal axis of the tool. It avoids formation of built up, edge, controls the direction of chip flow and distributes the cutting force and heat produced over larger cutting edge.

**Side relief angle.** It is the angle made by the flank of the tool and a plane perpendicular to the base just under the side cutting edge. This angle permits the tool to be fed side-ways into the job so that it can cut without rubbing. If the side relief angle is very large the cutting edge of the tool will break because of insufficient support whereas if the side relief angle is very small the tool can not be fed into the job, it will rub against the job and will get overheated and become blunt and the finish obtained on the job will be rough.

**End relief angle.** It is the angle between a plane perpendicular to the base and the end flank. This angle prevents the cutting tool from rubbing against the job. If the angle is very large the cutting edge of tool will be unsupported and will break off. Whereas if this angle is very small the tool will rub on the job, cutting will not be proper and poor finish will be obtained on the job. Its value varies from 6 to 10°.

**Nose radius.** The nose radius is provided to increase finish and strength of the cutting tip of the tool. Small radii will produce smooth finishes and are

used on thin cross-section of work. Large radii strengthen the tool and are used on cast iron and castings, where the cuts are interrupted.

Recommended tool angles for H.S.S. single point tools for some of the commonly used materials are indicated in Table 1.1.

Table 1.1

Material	Relief Angle (degrees)		Rake Angle (degrees)	
	Side	End	Back	Side
Aluminium	12—14	8—10	30—35	14—16
Brass (Free cut)	10—12	8—10	0	1—3
Cast Iron (Gray)	8—10	6—8	3—5	10—12
Copper (Commercial)	12—14	12—14	14—16	18—20
Steel	7—9	6—8	5—7	8—10

Recommended tool angles for carbide single point tool are indicated in Table 1.2.

Table 1.2

Material	Relief Angle (degrees)		Rake Angle (degrees)	
	Side	End	Back	Side
Aluminium	6—10	6—10	0—10	10—20
Copper	6—8	6—8	0—4	15—20
Brass	6—8	6—8	0—(-5)	8—(-5)
Cast Iron	5—8	6—8	0—(-7)	6—(-7)
Steel	5—10	5—10	0—(-7)	6—(-7)

### 1.5.2. Methods of holding tool

There are different ways of holding single point cutting tools. Tool directly fitted into tool holder is shown in Fig. 1.14 whereas Fig. 1.15 shows a tool fitted in a tool post.

The tool held by a clamp is shown in Fig. 1.16 and tool insert brazed to a tool shank is shown in Fig. 1.17.




Fig. 1.14




Fig. 1.15




Fig. 1.16




Fig. 1.17

### 1.6. Tool Signature

The tool angles have been standardised by the American Standards Association (A.S.A.). The seven important elements comprise the signature of the cutting tool and are stated in the following order.

Back rake angle, side rake angle, end relief angle, side relief angle, end cutting edge angle, side cutting end angle and nose radius. It is usual to omit the symbols for degrees and mm, simply starting the numerical value of each element. For example a tool having tool signature as 10, 10, 6, 6, 8, 8, 2 will have the following angles :

Back rake angle =  $10^\circ$

Side rake angle =  $10^\circ$

End relief angle =  $6^\circ$

Side relief angle =  $6^\circ$

End cutting edge angle =  $8^\circ$

Side cutting edge angle =  $8^\circ$

Nose radius = 2 mm.

#### 1.6.1. Requirements of a cutting tool

A cutting tool intended for high production machining should be possess the following requirements :

- (i) It should be amply strong and rigid.

- (ii) It should be keenly sharpened with a high class finish.
- (iii) It should have optimum geometry.
- (iv) It should be producible in manufacture and convenient in use.

The performance and economy of cutting tool mainly depend on the following :

- (i) Cutting tool material properties.
- (ii) Geometry of cutting tool.
- (iii) Methods used for mounting, clamping, indexing and change over for cutting tools.

The operational characteristics of a cutting tool are described by machinability produced. There are three main aspects of machinability

- (i) Tool life
- (ii) Surface finish
- (iii) Power required to cut.

### 1.7. Two systems of Defining the cutting Angles of a Single Point Tool

The cutting angles of a single point tools are commonly defined in two systems called *L-M-N* planes and *X-Y-Z* planes. The *L-M-N* plane system is chosen in reference to three mutually perpendicular planes. The plane *L* called as cutting plane being a vertical plane is tangent to the cutting edge of the tool. The plane *M* called as orthogonal plane being a vertical plane is perpendicular *L* plane. The plane *N* called as base plane is a horizontal plane being perpendicular to *L* and *M* planes. The various angles according to this shown in Fig. 1.18 are as follows :

$\alpha$  = Side relief angle.

$\beta$  = Wedge angle.

$\gamma$  = Orthogonal rake angle.

$\delta$  = Cutting angle =  $\alpha + \beta$ .

$\phi_1$  = Auxiliary cutting edge angle.

$\theta$  = Nose angle.

$\phi$  = Plane approach angle. (Principal cutting edge angle).

$\lambda_1$  = Inclination angle.

$\alpha_1$  = End relief angle.

$\beta_1$  = Side wedge angle.

$\gamma_1$  = Side rake angle.

This system is also known as International Orthogonal System of designating tool angles.

02723




Fig. 1.18. Tool angles in *L-M-N* plane.

The various angles in *X-Y-Z* systems are shown in Fig. 1.19. The system is the most popular system. This system is also called American system of tool nomenclature.




Fig. 1.19. Tool angles in *X-Y-Z* planes.

- $\alpha_y$  = Back rake angle.
- $\beta_y$  = End relief angle.
- $\alpha_x$  = Side rake angle.
- $\beta_x$  = Side rake angle.
- $\theta$  = Nose angle.
- $\phi_z$  = Side cutting edge angle.
- $\phi_1$  = End cutting edge angle.

Inter-relationship between different angles of system *L-M-N* and system *X-Y-Z* is as follows :

$$\tan \lambda = \tan \alpha_y \sin \phi - \tan \alpha_x \cos \phi$$

$$\tan \alpha_x = \sin \phi \tan \gamma - \cos \phi \tan \lambda$$

$$\tan \alpha_y = \cos \phi \tan \gamma + \sin \phi \tan \lambda$$

$$\tan \gamma = \tan \alpha_y \cos \phi + \tan \alpha_x \sin \phi$$

Normal rake angle ( $\gamma_n$ ) is given by



$$\tan \gamma_n = \tan \gamma \cos \lambda.$$

### 1.8. Types of Metal Cutting Process

The metal cutting processes are of two types :

- (i) Orthogonal cutting process (two dimensional cutting).
- (ii) Oblique cutting process (three dimensional cutting).


**Orthogonal cutting.** Orthogonal (two dimensional) cutting occurs when the major cutting edge of the tool is presented to the work piece






perpendicular to the direction of feed motion. Orthogonal cutting involves only two forces and this makes the analysis of cutting motion much easier. (Fig. 1.20).

**Oblique cutting.** This form of cutting occurs when the major edge of cutting tool is presented to the work piece at an angle which is not perpendicular to the direction of feed motion (Fig. 1.21).



(a)



(b)

Fig. 1.21. Oblique cutting.

### 1.8.1. Comparison of orthogonal and oblique cutting

These two methods are compared as follows :

Orthogonal cutting	Oblique cutting
(i) The cutting edge of the tool remains normal to the direction of tool feed.	The cutting edge of the tool is inclined at an acute angle to the direction of tool feed.
(ii) The direction of chip flow velocity is normal to the cutting edge of the tool.	The direction of chip flow velocity is at an angle with the normal to the cutting edge of the tool.
(iii) The cutting edge clears the width of the workpiece on either ends.	The cutting edge may or may not clear the width of the workpiece.
(iv) Only two components of cutting forces act on the tool. These two components are perpendicular to each other.	Three mutually perpendicular components of cutting forces act at the cutting edge of the tool.

### 1.9. Chip Formation

The type of chip produced during metal cutting depends upon the machining conditions and material being cut. The variable which influence the type of chip produced are as follows :

- (i) Properties of material cut especially ductility
- (ii) depth of cut
- (iii) feed rate
- (iv) effective rake angle of tool
- (v) cutting speed
- (vi) type and quantity of cutting fluid.

Factors like surface finish of tool faces, coefficient of friction between tool and chip, and temperature reached in the region of cutting also have some influence on chip formation but are generally less significant as compared to variables listed above.

Three different type of chips formed during metal cutting are as follows :

- (i) Continuous chip
- (ii) Discontinuous chip
- (iii) Continuous chip with a built up edge.

**Continuous chip.** A continuous chip is obtained when cutting ductile materials such as low carbon steel, aluminium and copper. This chip is severely deformed and either comes off in the form of a long string, or curls into a tight roll (Fig. 1.22).

Some very soft and ductile materials with a low strength tend to tear away from the parent metal of the workpiece rather than shear clearly. This results in a rough surface that has to be cleaned up by a very keen cutting edge. In addition to ductile workpiece material the other conditions which favour their formation are fine feed, sharp cutting edge, higher cutting speeds and larger rake angles.




Fig. 1.22. Continuous chip.

**Discontinuous chip.** Brittle materials such as grey cast iron, lack the ductility necessary for appreciable plastic chip formation. Consequently the compressed material ahead of tool fails in a brittle manner along the shear zone producing small fragments. Such chips are called discontinuous chips. (Fig. 1.23). Lower cutting speeds and insufficient rake angles cause the formation of such chips.




Fig. 1.23. Discontinuous chip.

**Continuous chips with a built up edge.** When during cutting, the temperature and pressure is quite high it causes the chip material to weld itself to the tool face near the nose (Fig. 1.24). This is called "Built up edge". This accumulated build up of chip material will then break away, part adhering to the underside of the chip and part to the workpiece. This process gives rise to a poor finish on the machined surface and accelerated wear on the tool face.

High friction at tool face, coarse feed, low rake angle and ineffective use of cutting fluid produce such chips.




Fig. 1.24

### 1.9.1. Areas in metal cutting

The important areas of interest in metal cutting are shown in Fig. 1.24 (a). First area ( $A_1$ ) extends along the shear plane and is the boundary between the deformed and undeformed material or the chip and the workpiece. The second area ( $A_2$ ) includes the interface between the chip and the tool face. While the third area ( $A_3$ ) includes the finished or machined surface and the material adjacent to that surface.




Fig. 1.24 (a)

The important aspect in first area ( $A_1$ ) is the plastic deformation characteristics of the material cut, whereas in second area ( $A_2$ ) the friction and wear characteristics of the tool workpiece combination and the important aspect in third area ( $A_3$ ) is the surface roughness produced and the residual stresses involved in the surface constituting the area.

### 1.10. Chip Thickness Ratio

The outward flow of the metal causes the chip to be thicker after separation from the parent metal. Metal prior to being cut is much longer than the chip which is removed (Fig. 1.25).




Fig. 1.25

Let  $t_1$  = chip thickness before cutting

$t_2$  = chip thickness after cutting

chip thickness ratio,  $r = \frac{t_1}{t_2}$

The chip thickness ratio or cutting ratio is always less than unity. If the ratio  $r$  is large, the cutting action is good. A ratio of 1 : 2 yields good results

$k$  = chip reduction coefficient

$$= 1/r$$

when metal is cut there is no change in the volume of the metal cut.

$$t_1 \cdot b_1 \cdot l_1 = t_2 \cdot b_2 \cdot l_2$$

$t_1$  = chip thickness before cutting (Depth of cut)

where  $b_1$  = width of cut

$l_1$  = length of chip before cutting

$t_2$  = chip thickness after cutting

$b_2$  = width of chip after cutting

$l_2$  = length of chip after cutting

It is observed that  $b_1 = b_2$

$$\therefore t_1 \cdot l_1 = t_2 \cdot l_2$$

$$\frac{t_1}{t_2} = \frac{l_2}{l_1} = r.$$

Although chip thickness ratio can be obtained by measuring chip thickness ( $t_2$ ) and depth of cut ( $t_1$ ) this is not the most precise procedure. Chip thickness ratio can be easily obtained by measuring  $l_1$  and  $l_2$ .

From the right angle triangle  $ABC$  (Fig. 1.25), we have

$$\frac{BC}{AB} = \sin \beta$$

$$AB = \frac{BC}{\sin \beta} = \frac{t_1}{\sin \beta} \quad \dots(i)$$

From right angle triangle  $ABD$

$$\frac{BD}{AB} = \sin (90 - \beta + \alpha) = \cos (\beta - \alpha)$$

or  $\frac{t_2}{AB} = \cos (\beta - \alpha)$

$$\frac{t_2}{\cos (\beta - \alpha)} = AB \quad \dots(ii)$$

From (i) and (ii) we get

$$\frac{t_1}{\sin \beta} = \frac{t_2}{\cos (\beta - \alpha)}$$

$$\frac{t_1}{t_2} = r = \frac{\sin \beta}{\cos (\beta - \alpha)}$$

$$= \frac{\sin \beta}{\cos \beta \cos \alpha + \sin \beta \sin \alpha}$$

$$r = \frac{\sin \beta}{\cos \beta \cos \alpha + \sin \beta \sin \alpha}$$

$$\frac{r \cos \beta \cos \alpha}{\sin \beta} + \frac{r \sin \beta \sin \alpha}{\sin \beta} = 1$$

$$\frac{r \cos \alpha}{\tan \beta} + r \sin \alpha = 1$$

$$\frac{r \cos \alpha}{\tan \beta} = 1 - r \sin \alpha$$

$$\tan \beta = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

Shear angle can be measured by measuring chip thickness, depth of cut and rake angle of tool. This can be most conveniently solved with the help of nomograph shown in Fig. 1.26 for determining shear angles.

### 1.11. Chip Breaker

Chip breakers are provided to control the continuous ribbon-like chips that are formed at high cutting speeds. Continuous chips are dangerous to the operator of the machine. These chips are hard, sharp and hot. They become entangled around the revolving job and the cutting tool. The chip breaker deflects the chip at a sharp angle and causes it to break into small pieces. So




Fig. 1.26. Nomograph for Shear Angles.

that they are easily removed by the coolant or air or simply allowed to fall into the chip pan of the machine.

There are basically two types of chip breakers :

- (i) Groove type
- (ii) Obstruction type.

Fig. 1.27 shows the groove type chip breaker.

Chip breaker




Fig. 1.27

Fig. 1.28 shows an obstruction type chip breaker.

Chip breaker




Fig. 1.28

### 1.12. Radius of Chip Curvature

In an obstruction type chip breaker the chip starts to curl away from the tool face at the end of chip tool contact region and that the chip then maintains a constant radius of curvature until it clears the chip breaker. (Fig. 1.29). The radius of the chip curvature can be found by the following formula.

$$R = \frac{(S - H)^2}{2h} + \frac{h}{2}$$

where  $R$  = Radius of chip curvature

$S$  = Chip breaker distance

$H$  = Length of chip tool contact

$h$  = Chip breaker height.

It is observed that larger shear angles require less cuttings forces than smaller shear angles because smaller the shear angle the greater thickness of the material which the fracture plane need to traverse. (Fig. 1.30) the shear angle is a function of the rake of the tool, the material being cut and the friction at the face of the tool. As shown  $t_3 > t_2 > t_1$  and shear angle  $\beta_2 < \beta_1$ . The chip thickness is  $t_2$  when shear angle is  $\beta_1$  and chip thickness is  $t_3$  when shear angle is  $\beta_2$ .




Fig. 1.29




Fig. 1.30

**Curling of Chip.** The chip curls into a spiral because the layer adjoining the tool is deformed. It can be seen in Fig. 1.31 that on the side facing the force  $P$  the layer becomes thicker and acquires a wedge shape as a result of which the curvature (curling) is produced. Another reason for curling the chip is that in meeting the tool face a change in its direction of flow away from tool face takes place curling is also produced by the non-uniform cooling of the chip throughout its thickness. Depending upon the machining conditions the chip may cut into a flat (logarithmic) spiral or into a helix.





Fig. 1.31

**1.13. Chip Reduction Coefficient**

The chip produced during metal cutting turns out to be shorter than the part of the work from which it has been cut (Fig. 1.32) because of the plastic compression of the layer of metal being cut. This shortening of the chip is




Fig. 1.32. Chip contraction.

known as longitudinal chip contraction and its magnitude is characterised by the coefficient of contraction.

- Let,  $K$  = Chip reduction co-efficient  
 $L_1$  = Length of the section of the work from which chip was removed in mm  
 $L_2$  = Length of chip cut from the section in mm  
 $K = \frac{L_1}{L_2}$

The value of  $K$  may be as high as 6 to 8 depending upon the machining conditions. The coefficient of chip contraction is a certain quantitative measure

of the degree of plastic deformation in metal cutting smaller value of chip contraction coefficient indicates less plastic deformation in cutting process and this will require less power consumption to machine the given workpiece. Chip contraction depends upon the following factors :

- (i) Cutting variables such as cutting speed, feed and depth of cut.
- (ii) Geometry of cutting tool.
- (iii) Type of cutting fluid used.
- (iv) Type of material of work piece and its mechanical properties.

It is observed that the greater the cutting angle (or the smaller the positive rake angle) the greater the contraction. An increase in nose radius leads to greater chip contraction. Fig. 1.33 shows the effect of cutting speed (V) on chip reduction coefficient K. With an increase in cutting speed contraction is first reduced, reaching a minimum and then increases reaching a




Fig. 1.33




Fig. 1.34

maximum after which it drops again. Fig. 1.34 shows variation of chip reduction coefficient with feed upon an increase in feed coefficient of chip reduction is usually reduced.

The effect of surface active cutting fluids is clearly manifested is the reduction of chip contraction (Fig. 1.35).




Fig. 1.35

1.14. Cutting Speed, Feed and Depth of Cut

**Cutting speed.** It is the travel of a point on the cutting edge relative to the surface of cut in unit time in the process of accomplishing the primary cutting motion. For example in lathe work when a workpiece of diameter D rotates at a speed N revolutions per minute the cutting speed (V) is given by the relation

$$V = \frac{\pi \cdot D \cdot N}{1000} \text{ m per min.}$$

where D = Diameter of workpiece in mm.

**Feed.** The feed or more precisely rate of feed is the amount of tool advancement per revolution of job parallel to the surface being machined. Feed is expressed either as the distance moved by the tool in one minute. It is expressed in millimetres per revolution. On a shaper feed is the distance the work is moved relative to the tool for each cutting stroke. Feed is expressed as millimeters per tooth for milling cutters and broaches. Feed depends on depth of cut, rigidity of cutting tool and type of cutting tool material. Higher feeds are used in roughing cuts, rigid set-ups, soft materials, rugged cutters

and heavy machine tools. Lower feeds are used for finishing cuts, frail set-ups, hard work materials and weak cutters. Normally feed varies from 0.1 to 1.5 mm.

In milling a good commercial surface finish can be obtained by using a feed rate of 0.75 mm to 1.25 mm per revolution of the cutter. Finer feeds such as 0.4 mm per revolution of cutter will result in an excellent surface finish.

Table 1.3 shows cutting speed and feed for H.S.S. turning tools for machining some of the materials.

Table 1.3

Material to be machined	Cutting speed (m/min)	Feed (mm/rev)
Aluminium	70—100	0.2—1.00
Brass (Free cutting)	70—100	0.2—1.5
Copper	35—70	0.2—1.00
Grey Cast Iron	25—40	0.15—1.7
Mild Steel	35—50	0.2—1.00

In lathe work distinction is made between longitudinal feed when the tool travels in a direction parallel to the work axis and cross feed when the tool travels in a direction perpendicular to the work axis.

Feed of a lathe and similar machine tools is the distance the cutting tool is fed for each revolution of work. The feed of drilling machine is the rate at which drill is advanced into the work piece per revolution of drill. The feeds for reaming operation is usually higher than that used for drilling because reamers have more teeth and a reaming operation is used for sizing and finishing. The feed of shapers and planers is the distance the cutting tool advances at the end of each cutting stroke. Feed of a milling machine is expressed in millimeter per minute of table movement.

The maximum feed is limited by the following factors :

- (i) Cutting edge strength
- (ii) Rigidity and allowable deflection
- (iii) Surface finish required
- (iv) Tool chip space.

Use of proper cutting fluid permits higher feeds and increased cutting speeds as well as attainment of better surface finish.

Feed is measured in different units as follows :

- (i) mm/Rev in machine tools with rotary drive motion such as lathes, boring machines.
- (ii) mm/stroke in machine tools with reciprocating drive motion such as shaper, planer.
- (iii) mm/tooth in machine tools using multiple tooth cutters such as milling machine.

Let,  $f =$  Feed per revolution or feed per stroke  
 $f_m =$  Feed per minute  
 $= f \times N$

where  $N =$  Number of revolutions or strokes per minute

Feed per tooth in multiple tooth cutters is related to the feed per revolution as follows :

$$f = f_t \times z$$

where  $f_t =$  feed per tooth of cutter

$z =$  Number of teeth on cutter.

The machining time to carry out any operation on a machine tool is determined as follows :

$$T = \text{Machining Time (minutes)} \\ = \frac{L}{f_m}$$

where  $L =$  length of machine surface (millimetre)

$f_m =$  Feed per minute.

**Depth of cut.** It is the thickness of the layer of metal removed in one cut or pass measured in a direction perpendicular to the machined surface. The depth of cut is always perpendicular to the direction of the feed motion.

In external longitudinal turning it is half the difference between the work diameter ( $D_1$ ) and the diameter of the machined surface ( $D_2$ ) obtained after one pass.

$$t = \text{Depth of cut} = \frac{D_1 - D_2}{2} \text{ mm.}$$

Fig. 1.36 shows cutting speed ( $v$ ), depth of cut ( $t$ ) and feed ( $f$ ) for lathe, milling machine, drill machine and shaper.




Fig. 1.36

In general speed and feed depend upon the following factors :

- (i) Type of material of workpiece.
- (ii) Type of material of cutting tool.
- (iii) Quality of finish desired.
- (iv) Type of coolant used.
- (v) Rigidity of the machine tool.

Table 1.4 shows typical lathe turning speeds for ceramic tools.

**Table 1.4**

Material to be cut	Roughing (m/min)	Finishing (m/min)
Upto 0.2 Carbon Steel	130—260	320—240
0.2 to 0.3 Carbon Steel	100—200	260—320
0.3 to 0.4 Carbon Steel	80—160	230—300
0.4 to 0.6 Carbon Steel	65—100	130—200
Cast Iron (BHN 217)	160—320	320—500

### 1.15. Objectives of a Good Tool Design

A cutting tool should be made up of proper material and should be accurately designed in order to achieve the following objectives.

- (i) Easy chip flow.
- (ii) Proper surface finish and accuracy.
- (iii) High productivity.
- (iv) Less amount of input power.
- (v) Minimum overall cost.

The tool designed should have sufficient strength to maintain a sharp cutting edge during cutting and should have sufficient hardness to prevent picking up the chips.

### 1.16. Cutting Tools Materials

The purpose of cutting tool material is to remove metal under controlled conditions. Therefore the tool must be harder than the material which it is to cut. The cutting tools are made up of different materials. The cutting tool material should possess the following requirements :

- (i) It should be strong enough to withstand the forces being applied due the cutting *i.e.* bending compression, shear etc.
- (ii) It should be tough (resistant to shock loads). It is quite important when tool is used for intermittent putting.
- (iii) It should be sufficient harder (resistant to wear, abrasion and indentation) the material being cut.
- (iv) It should be able to resist high temperature.
- (v) It should be capable of withstanding the sudden cooling effect of coolant used during cutting.
- (vi) The coefficient of friction between the chip and the tool should be as low as possible in the operating range of speed and feed.

(vii) It should be easily formed to the required cutting shape.

Material chosen for a particular application will depend on the material being machined, the quantity of components to be produced, the cost of cutting tool materials, the type of machining operation (intermittent or continuous roughing or finishing, high or low speed etc.), the tool design details (cutting and clearance angles method of holding rigidity etc.) and the general conditions of machine tool.

Several materials exhibiting above properties in varying degrees have been developed for use in cutting tools.

The following metals suitably heat treated wherever required (tungsten carbide and ceramics are not heat treatable) are used in the manufacture of cutting tools :

- (a) Carbon tool steel.
- (b) High speed steel.
- (c) Cemented carbides.
- (d) Ceramics.
- (e) Diamonds.

**Carbon tool steels.** Carbon steels are limited in use to tools of small section operating at lower speeds. A typical plain carbon steel used for cutting tool has the following composition.

C = 0.8 to 1.3%, SI = 0.1 to 0.4%, Mn = 0.1 to 0.4%.

Such steels when hardened and tempered have good hardness, strength and toughness and can be given a keen cutting edge. Tools made up of plain carbon steel can be used for machining soft materials such as free cutting steels and brass. This material starts losing its hardness at about 250°C and is therefore not used when the operational temperature is more.

**High speed steels.** High speed steel tools give improved cutting performance and higher metal removal rates. High speed steel is widely used for drills, many types of general purpose milling cutters and single-point tools.

Although several types of high speed steels are in use but 18-4-1 high speed steel containing tungsten 18%, chromium 4% and vanadium 1% is quite commonly used. This type of material gives excellent performance over a great range of materials and cutting speeds and it retains its hardness upto around 600°C. The coolant should be used freely to increase tool life. The chief characteristics of high speed steels are superior hardness and wear resistance.

Sometimes, the surface of high speed steel tools are treated by the following methods to reduce friction and to increase wear resistance.

- (i) Super finishing (to reduce friction).
- (ii) Chromium of electrolytic plating (to reduce friction).
- (iii) Oxidation (to reduce friction).
- (iv) Nitriding (to increase wear resistance).

Table 1.5 indicates some of the carbon tool steels.



Table 1.5. Carbon Tool Steels

IS : 1570/1961 Designation	Nominal Chemical Composition						
	C%	Mn%	Si%	S%	P%	Cr%	V%
T 70	0.70	0.25	0.20	0.03	0.03	—	—
T 80	0.80	0.25	0.20	0.03	0.03	—	—
T 90	0.90	0.25	0.20	0.03	0.03	—	—
T 103	1.00	0.25	0.20	0.03	0.03	—	—
T 118	1.15	0.25	0.20	0.03	0.03	—	—
T 133	1.30	0.25	0.20	0.03	0.03	—	—

Table 1.6 shows some of popular grades of high speed steels used for making tools.

Table 1.6. High Speed Steel

IS : 1570/1961 Designation	Nominal Chemical Composition										
	C%	Mn%	Si%	S%	P%	Cr%	Ni%	Mo%	W%	V%	CO%
T70W18Cr4V1	0.70	0.40	0.35	0.25	0.025	4.15	—	—	18.25	1.20	—
T75W18Co6	0.75	0.40	0.35	0.25	0.025	4.20	—	0.75	18.25	1.25	5.50
Cr4VIMo75	—	—	—	—	—	—	—	—	—	—	—
T83Mo6W6Cr4 V2	0.83	0.40	0.35	0.25	0.025	4.10	—	5.50	6.00	1.90	—

**Cemented carbides.** They consist of tungsten, tantalum and titanium carbides together with a binder usually cobalt all mixed together as fine powders. These powders are compacted (compressed) into the required shape and subjected to a high temperature treatment known as sintering. During this process the cobalt binder is fused to the carbides, producing a hard, dense substance.

Tools made up of cemented carbides are extremely hard having Rockwell hardness varying from 90—93 HRC. They can be used at cutting speeds 200 to 500% greater than those used for high speed steel. They have virtually replaced high speed steels in high speed and high producing machining. Cemented carbides are very hard and the usual practice is to confine the size to a relatively small shape known as an “insert” which is clamped to a tough steel shank or holder. This has the advantage that the tool bit is well supported to resist the cutting forces. This insert may have three to eight edges and is so designed that each of its cutting edges can be used in turn. It may then be discarded and replaced with a new tool bit giving low maintenance and breakdown time.

The general characteristics of carbide tools are as follows.

- (i) They have high thermal conductivity, low specific heat and low thermal expansion.
- (ii) They have high hardness over a wide range of temperature (up to 900°C).
- (iii) Their compressive strength is more than tensile strength.
- (iv) They are very stiff. Their Young's modulus is about three times than steel.

**Ceramics.** Aluminium oxide and boron nitride powders mixed together and sintered at 1700°C form the ingredients of ceramic tools. These materials are very hard with good compressive strength. Ceramics are usually in the form of disposable tips. They can be operated at from two to three times the cutting speeds of tungsten carbide and cutting speeds on cast iron in the order of 1000 m/min are not uncommon. They resist cratering, usually require no coolant. However in order to take full advantage of their capabilities special and more rigid machine tools are required.

Ceramic and cemented carbide cutting tools should be sharpened to a high degree of surface finish to minimise friction between tool and chip. This will improve to efficiency of the cutting process and less power will be absorbed and there will be a less tendency for a built up edge to form on the cutting face of the tool.

Cemented carbide or ceramic tips can be brazed to medium carbon steel shank and resharpened by grinding when necessary. For many applications it is more economical to clamp the tip to the shank (Fig. 1.37). The

technique enables a tip to be thrown away (called throw away tips) at the end of its useful life and new tip to be clamped to the existing shank.




Fig. 1.37

The various conditions for the effective use of carbide or ceramic tool are as follows :

- (i) Rigidity of tool and workpiece.
- (ii) Highly finished surface on cutting tool.
- (iii) High cutting speeds.
- (iv) Use of machine tool having high quality bearings.
- (v) Use of effective chip bearings.
- (vi) Elimination of any unbalanced forces
- (vii) Chip guards are essential when using these tools.

**Diamonds.** Diamond is the hardest material known. It has a low coefficient of friction, high compressive strength and is extremely wear resistant. It is used mainly for cutting very hard materials, such as glass, plastics, ceramics etc. Diamond tools produce a very good surface finish at high speeds with good dimensional accuracy. Diamond tools are small and are best suited for light cuts and finishing operations. Other application for diamond is that it is used for truing the grinding wheels. The general properties of diamond may be summarised as follows :

1. It is the hardest known substance.
2. It has lowest thermal expansion of any pure substance.
3. It has high heat conductivity.
4. It is poor electrical conductor.
5. It has very low coefficient of friction against metals.

Since very high hardness is always accompanied by brittleness a diamond tool must be cautiously used to avoid rupturing the point. This usually limits the use of diamond tools to light continuous cut in relatively soft metals and low values of rake angle are usually used to provide a stronger cutting edge.

The main disadvantages of diamonds are their brittleness and high cost.

### 1.17. Variation of Hardness with Temperature

Fig. 1.38 shows the variation of hardness with temperature for the tools made up of different materials.

1. A plain carbon tool steel tool.
2. An 18-4-1 high speed steel tool.
3. A cast alloy tool.
4. A cast iron grade cemented tungsten carbide tool.

### 1.18. Economic Comparison of Tool Materials

The principal tool materials are high speed steel, cemented carbide and ceramics in increasing order of hardness and reducing order of toughness. High speed steel is quite commonly used as it can be used to manufacture complicated shaped cutting tools such as drills, taps, reamers, dies and milling cutters. Cemented carbide because of its high cost and need to form it in its final shape has limited applications and is generally used for rough or finish turning and face milling operations. Ceramic tool material is brittle, cannot withstand high force and is generally used in finish turning operations.




Fig. 1.38

Properties of tool materials are basically governed by the following :

- (i) Chemical composition of the materials.
- (ii) Type and size of grains of materials before manufacture.
- (iii) Manufacturing process.
- (iv) Finishing treatments.

### 1.19. Multi-edge Cutting Tools

Multi-edge cutting tools present more than one cutting edge to the work. They have a higher metal removal rate than single edged cutting tools

and also the life of the multi-edge cutting tool is raised by increasing the number of cutting edges. The different multi-edge cutting tools are divided into two groups as shown in table 1.7. A grinding wheel is also a form of multi-edge cutting tool.

Table 1.7

Group	Machines	Cutting Tools
A	Drills	Twist drills
	Capstan	Reamers
	Lathe	Multi-flute core drills
	Turret	Counter bores spot
	Lathe	Facing cutters.
B	Milling Machines	Saws and slotting cutters
		Side and face cutters
		Slab mills
		End mills
		Face mills
		Form-relieved cutters.

The tools in group A have their cutting edges in continuous engagement with the work and are fed axially at a uniform feed per revolution. The underformed chip thickness is therefore constant and directly proportional to the feed/rev. The geometry and mechanics of cutting are then identical with those discussed for single point tools. The various tools in group B have their cutting edges intermittently engaged with the work and are fed in a plane parallel or perpendicular to the cutter axis of rotation.

### 1.20. The Twist Drill

It is used to produce a hole in the workpiece. Its sole purpose is to remove the maximum volume of metal in a minimum period of time. The finish obtained by a drill is not so fine. If a hole of accurate size and good finish is required the drilled hole should be finish machined by means of a reamer or by single point boring tool. Twist drills are usually made of high speed steel. High carbon steel can also be used to manufacture drills. Drills with cemented carbide cutting tips (tips are brazed) are used at very high speeds for drilling operations on non-ferrous metals but are not recommended for ferrous metal particularly steels because the tips are not supported as effectively as in case of single point cutting tools or milling cutters. A twist drill consists of a cylindrical body carrying two helical grooves into it to form the flutes. The

flutes run the full length of body of twist drill and perform the following functions :

- (i) They provide the rake angle.
- (ii) They form the cutting edges.
- (iii) They provide a passage to the coolant.
- (iv) They facilitate swarf removal.

### 1.21. Elements of a Twist Drill

A twist drill is shown in Fig. 1.39. The various elements of a twist drill are as follows :

- (i) **Body.** It is the part of the drill that is fluted and relieved
- (ii) **Shank.** It is the part held in the holding device.




Fig. 1.39. Elements of a twist drill.

The most common types of shanks are the taper shank and the parallel shanks. Small drills up to about 12.7 mm diameter are provided with parallel




Fig. 1.40. The point of twist drill.

shanks and the larger size drill have tapered shanks. Tapered shank drill carry a tang at the end of the shank to ensure a positive grip. The straight shank drills are held in a drill machine by a chuck. The jaws of the chuck are tightened around the drill by means of a key or wrench. The point of a drill is the entire cone shaped surface at the cutting end of the drill. (Fig. 1.40).

(iii) **Dead centre.** The dead centre or chisel edge of the drill is the sharp edge at the extreme tip end of the drill. It should always be in the exact centre of the axis of the drill.

(iv) **Lip.** Lip or cutting edge is formed by the intersection of the flank and face. Both the lips of the drill should be of equal length and should be at the same angle of inclination with the drill axis. This will enable to produce a perfectly round smooth and accurate hole. Unequal lips will result in an oversize hole.

(v) **Flank.** Flank is the surface on a drill point which extends behind the lip to the following flute.

(vi) **Chisel edge corner.** The corner formed by the intersection of a lip and the chisel edge is called chisel edge corner.

(vii) **Flutes.** The grooves in the body of the drill which provides lips.

**Twist drill angles.** Like any other cutting tool the twist drill is provided with correct tool angles (Fig. 1.41). The various angles are as follows :

(i) **Rake angle or helix angle.** It is the angle of flute in relation to the work.

Smaller the rake angle greater will be the torque required to drive the drill at a given speed. Its usual value is  $30^\circ$  although it may vary up to  $45^\circ$  for different materials.

The rake angle also partially governs the tightness with which the chips curl and hence the amount of space which the chips occupy. Other conditions being the same, a very large rake angle makes a tightly rolled chip, while a rather small rake angle makes a chip tend to curl into a more loosely rolled helix.

(ii) **Lips clearance angle.** It is the angle formed by the flank and a plan at right angle to the drill axis. Lip clearance is the relief that is given to the cutting edges in the order to allow the drill to enter the metal without interference. This angle is  $12^\circ$  in most cases. In order to allow strength and rigidity to the cutting edge the clearance angle should be kept minimum.

(iii) **Cutting angle or point angle.** It is the angle included between the two lips projected upon a plane parallel to the drill axis and parallel to the two cutting lips. It is observed that the best point angle is  $118^\circ$ .

(iv) **Chisel edge angle.** It is the angle included between the chisel edge and the lip as seen from the end of the drill.




Fig. 1.41

The various angles for a drill are shown in table 1.8.

Table 1.8

Material	Point angle (Degrees)	Lip clearance angle (Degrees)	Chisel edge angle (Degrees)	Helix angle (Degrees)
Aluminium	90—140	8—12	120—135	24—48
Brass	111	8—15	120—135	0—27
Copper	100—118	8—15	120—135	28—40
Cast iron hard	118	8—12	120—135	24—40
Steel	118	8—12	120—135	24—32
Stainless Steel	125—135	10—12	120—135	24—32

## 1.22. Cutting Fluids for Drilling

Cutting coolants and oils are used during drilling to carry away the heat from the drill point preventing it from overheating. This permits higher cutting speeds and longer drill life. The action of chips coming out of the hole tends to restrict the entry of the fluid. A continuous supply of cutting fluid should be maintained in order to obtain proper cooling. For severe conditions drills containing oil holes have a considerable advantage. In such case not only the fluid is supplied near the cutting edges but the flow of fluid aids in chip removal from the hole.

Practically all metals require the use of coolant when being drilled except cast iron which may be machined dry.

## 1.23. Twist Drill Grinding

It is very important that drills are properly ground. The drill point must be in the centre of rotation of the drill. The lips should be of equal length and

at correct angle with the axis. The twist drill is ground on the side of grinding wheel of the grinding machine as shown in Fig. 1.42 (a). The flat surface that this provides makes it much easier to generate a true point. The straight cutting lip should lie vertically against the side of the wheel when the drill has been




Fig. 1.42

ground it should be checked on a point gauge. Fig. 1.42 (b) shows a twist drill point angle and lip length gauge. If the lips are of unequal length the result will be that both the point and lip will be off-centre (Fig. 1.43). This will cause the hole to be large than the drill. If a drill is ground with its tip on the centre but with the cutting edges at different angles the drill will bend on one side of the hole (Fig. 1.44). Only one lip or cutting edge will do the work resulting in rapid wear on that edge and the hole will be larger than drill.




Fig. 1.43

Fig. 1.44

1.23.1. Twist drill failure

A twist drill will suffer an early failure or produce holes that are dimensionally inaccurate, out of round and poor finish for the following general reasons :

- (i) Incorrect speed and feeds
- (ii) Incorrect grinding of the point
- (iii) Mishandling.

1.24. Rake and Relief Angles of a Twist Drill

**Rake Angle.** The rake angle ( $\alpha$ ) is the angle between the tangent to the face (in the flute) at the point of lip (cutting edge) being referred to and the normal at the same point to the surface of revolution described by the lip about the drill axis. The rake angle is measured in a plane perpendicular to the lip (plane mm in Fig. 1.45). This angle varies gradually along the lip. It can be found by using the following relation :

$$\tan \alpha_x = \frac{r_x \tan \beta}{R \sin \theta}$$

where  $\beta$  = Helix angle of flutes.

$R$  = Radius of drill.

$\theta$  = One half of the point angle.

$r_x$  = Radius of the circle on which the point being considered is located.

$R$  = Radius of the drill.

Angle  $\alpha$  acquires its maximum value at the periphery of the drill. The variation of rake angle along the lip is shown by a graphical construction.




Fig. 1.45

Fig. 1.46

Refer Fig. 1.46. When a helix is developed on a plane it will become the hypotenuse of a right triangle of which one side is the lead (pitch) of the flutes and the other side is the circumference of a circle of a diameter ( $D$ ) on which the helix was formed.

**Relief Angle  $\gamma$ .** It is the angle between a tangent to the flank or lip relief surface at the point being considered on the lip and a tangent at the same point to the circle the point describes as it rotates about the drill axis. This angle is measured in plane  $NN$  (Fig. 1.45) which is tangent to the cylindrical surface on which the above mentioned point on the lip lies.

### 1.25. Drill Specifications

According to Indian Standard System, twist drills are specified by the diameter, the I.S. number, the material and the series to which they belong. The drills are made in three types :

- (i) Type  $N$ —for normal low carbon steel.
- (ii) Type  $H$ —for hard materials.
- (iii) Type  $S$ —for soft and tough materials.

For example a parallel shank twist drill 12 mm diameter and made up of high speed steel and conforming to IS : 5101 with a point angle of  $118^\circ$  and of  $N$ -type is designated as 12.00—IS : 5101 HS-N-118.

Unless otherwise mentioned in the designation it should be assumed that drill type is  $N$  and point angle is  $118^\circ$ .

**Drill Size.** In metric system the drills are made in diameters from 0.2 mm to 100 mm.

### 1.26. Cutting Speed, Feed and Depth of Cut

**Cutting speed.** It is the peripheral speed of a point on the surface of the drill in contact with the work piece. It is usually expressed in metres per minute.

Let  $D$  = Diameter of drill in mm.  
 $N$  = R.P.M. of drill spindle.  
 $V$  = Cutting speed in metre per minute.  

$$V = \frac{\pi DN}{100} \text{ metre per minute.}$$

Cutting speed mainly depends upon the following factors :

- (i) Type of material to be drilled.
- (ii) Type of material of drill. Twist drill made of high speed steel can be operated at about twice the speed of drill made of high carbon steel.
- (iii) Type of finish required.
- (iv) Type of coolant used.
- (v) Capacity of machine and tool life.

Table 1.9 shows cutting speed for high speed steel drill.

Table 1.9

Material being drilled	Cutting speed (m/min)
Aluminium	70—100
Brass	35—50
Phosphor Bronze	20—35
Grey Cast Iron	25—40
Copper	35—45
Mild Steel	30—40
Alloy Steel (High tensile)	5—8

**Feed.** It is the distance the drill moves into the work at each revolution of the spindle. It is expressed as millimeter per revolution.

It may also be expressed as feed per minute.

Let  $N$  = R.P.M. of drill spindle.

$f$  = feed in mm/rev.

$f_1$  = feed in mm per minute.

$= N.f.$

Table 1.10 shows feed for high speed steel drill of various diameters.

Table 1.10

Drill diameter (mm)	Feed (mm/rev.)
1.0—2.5	0.04—0.06
2.6—4.5	0.05—0.10
4.6—6.0	0.075—0.15
6.1—12.00	0.75—0.25
12.1—15.0	0.20—0.30
15.1—18.0	0.23—0.33
18.1—21.0	0.26—0.36
21.1—25	0.28—0.39

A twist drill gives satisfactory performance if it is run at correct cutting speed and feed. The following factors help in running the drill at correct cutting speed and feed.

- (i) The work is rigidly clamped.
- (ii) The machine is in good condition.
- (iii) A coolant is used if required.

(iv) The drill is correctly selected and ground for the material being cut. The selection of drill depends upon the following.

- Size of drill hole
- Material of workpiece
- Point angle of drill.

The rates of feed and cutting speed for twist drill are lower than most other machining operations because of the following reasons.

- The twist drill is weak compared with other cutting tools.
- It is relatively difficult for the drill to eject chips.
- It is difficult to keep the cutting edges cool when they are enclosed in the hole.

**Depth of cut.** It is equal to one half of the drill diameter.

$D$  = Diameter of drill in mm.

$t$  = Depth of cut in mm.

$$= \frac{D}{2} \text{ mm.}$$

### 1.27. Machining Time

Machining time in drilling is calculated as follows (Fig. 1.47)

Let  $T$  = Machining time in minutes

$l$  = Thickness of workpiece in mm.

$h$  = Approach of drill =  $0.3D$  in mm

$D$  = Diameter of drill in mm.

$L$  = length of axial travel of drill =  $l + h$ .




Fig. 1.47

$f$  = feed/rev. in mm.

$$T = \frac{L}{N \times f}$$

### 1.28. Forces Acting on a Drill

The various forces acting on a drill are shown in Fig. 1.48. All the elements of a drill are subject to certain forces in drilling. Resolving the resultant forces of resistance to cutting at each point of the lip we obtain three forces  $F_Z$ ,  $F_V$ , and  $F_H$  acting in directions mutually perpendicular to each other. The horizontal forces  $F_H$  acting on both lips are considered to counter balance each other. The vertical force  $F_V$  also called as thrust force comprises of the forces  $F_{V_1}$ ,  $F_{V_2}$ ,  $F_C$  and  $F_m$ . (The forces  $F_C$  and  $F_m$  are not shown). The force

$F_{V_1}$ , acts on the web. This force is quite large and is about 60% of the total thrust force. This force  $F_{V_2}$  act on each of the two lips and forms the real cutting force which depends upon the work material, cutting variables and cutting point geometry and is about 37% of total thrust force. The  $F_C$  and  $F_m$  are of smaller magnitude. The force  $F_C$  is due to the rubbing of the chips, flow from the hole against the sides of the hole and flutes on the drill. This force is about 1% of the total thrust force. The force  $F_m$  is due to the rubbing action of margin of the drill against the sides of the hole and is about 2% of thrust force.

In order that the drill to penetrate into the work piece the thrust force  $F$  applied to it by the machine must over come the sum of resistances acting along the drill axis.

$$F > \Sigma(F_{V_1} + 2F_{V_2} + F_C + F_m)$$

The force  $F_Z$  sets up the moment of resistance ( $M_r$ )

$$M_r = F_Z \cdot S$$

The total moment of the forces of resistance ( $M$ ) to cutting is made up of the following moments.

- Moment of forces  $F_Z$  i.e.  $M_r$
- Moment of forces due to scraping and friction on the chisel edge ( $M_c$ )
- Moment of the friction forces on the margins ( $M_m$ )
- Moment of the forces of friction of the chip on the drill and on the machined surface ( $M_d$ )




Fig. 1.48

$$M = M_r + M_c + M_m + M_d.$$

The total moment of resistance should be overcome by the available torque of the drilling machine.

### 1.29. Power of Drilling

When a drill is cutting it has to overcome the resistance offered by the metal and a twisting effort is necessary to turn it. The effort is called turning moment or torque on the drill. The torque required to operate a drill depends upon various factors. The relationship between torque, diameter of drill and feed is as follows :

$$T_1 = C.f^{0.75} D^{1.8} \text{ newton metres}$$

where  $T_1$  = Torque in newton metre

$f$  = Drill feed in mm/rev.

$D$  = Diameter of drill in mm.

$C$  = Constant depending upon the material being drilled. The values of  $C$  are given in table 1.11 for different materials.

Table 1.11

Material to be drilled	Value of $C$
Aluminium	0.11
Soft brass	0.084
Cast Iron	0.07
Mild steel	0.36
Carbon tool steel	0.4

$$\text{Power } (P) = \frac{2\pi NT_1}{60,000} \text{ kW}$$

where  $N$  = Drill speed in R.P.M.

### 1.30. Milling Cutters

Milling is an operation in which metal cutting is carried out by means of multi-teeth rotating tool called cutter. The cutters are manufactured in a variety of shapes and size each made for a specific purpose. In milling cutters each tooth after taking a cut comes into operation again after some interval of time. This allows the tooth to cool down before the next cutting operation is done by it. This minimises the effect of heat developed in cutting on cutting edges. A coolant helpful when milling steel for producing a good surface finish. The coolant may be oil or an emulsion of oil and water. The form of each tooth of cutter is same as that of a single point tool.

Many types of milling cutters are used on a milling machine. Most of them are considered standard and are available in many sizes. High speed steel

is the material commonly favoured for cutters. They are also available with carbide tips as cutting edges. Cutters should be kept sharp. Cutters which are sharpened frequently usually last longer than those which are allowed to become dull.

A milling cutter is a multiple tooth tool and therefore higher requirements are made to its construction, sharpening and operation. The cutter should be reliably and rigidly clamped on the spindle. Milling cutters may be solid, inter locking, carbide tipped solid cutters and inserted blade cutters with high speed steel or carbide tipped blades.

The various advantages of carbide tipped cutters either solid or inserted blade type are as follows :

- (i) They have high production capacity.
- (ii) They produce surface finish of high quality.
- (iii) They can machine hardened steels.
- (iv) Their use leads to reduction in machining costs.

With cylindrical cutters the two methods of milling operation commonly used are as follows :

(i) **Up or conventional milling.** In this process the cutter rotates against the direction in which the work is feeding (Fig. 1.49).




Fig. 1.49. Up milling.

(ii) **Down milling or Climb milling.** In this process the cutter rotates in the same direction as that in which the work is feeding (Fig. 1.50). The machine in which high velocity milling is to be done should not only be capable of operating at high speeds and feeds but should also possess ample rigidity. The cutter should be reliable and rigidly clamped on the spindle.






Fig. 1.50. Down milling.

**1.31. Elements of a Plain Milling Cutter**

A milling cutter may have either straight teeth *i.e.* parallel to the axis of rotation or in helical shape. A milling cutter can be considered as a built up unit of a number of single point cutting tools such that each tooth of the cutter is a single point cutting tool. Fig. 1.51 shows a plain milling cutter. The various parts of the cutter teeth are face, cutting edge, fillet, and body.




Fig. 1.51. Elements of plain milling cutter.

The various elements of the cutter are as follows :

(i) **Lip angle.** It is the angle included between the land and the face of the tooth or it is the angle between the tangent to the back at the cutting edge and the face of the tooth.

(ii) **Relief angle.** The angle in a plane perpendicular to the axis which is the angle between the land of a tooth and the tangent to the outside diameter of cutter at the cutting edge of that tooth.

The main function of relief angle is to prevent interference between land and work surface. The relief angle varies with the type of material being milled. Table 1.12 indicates the relief angles for different materials.

**Table 1.12**

Material	Relief angle (Degree.)
Cast Iron	4—7
Mild Steel	3—6
Brass	10—12
Aluminium alloys	10—12

(iii) **Rake angle (Radial).** It is the angle measured in the diametral plane between the face of the tooth and radial line passing through the tooth cutting edge. It facilitates free cutting by tool allowing the chip to flow smoothly. This ensures less power consumption and better surface finish, less wear and hence more life of tool. It may be positive, negative or zero.

Table 1.13 indicates the rake angles in degrees for different materials to be milled.

**Table 1.13**

Material	Cemented carbide cutter	H.S.S. Cutter
Aluminium alloys	10—20	20—35
Cast Iron		
Hard	0—3	8—10
Soft	3—6	10—15
Mild Steel	0—(-5)	10—15
Brass	3	10

(iv) **Primary clearance angle.** It is the angle between a line passing through the surface of the land and a tangent to the periphery at the cutting edge. This angle is provided to prevent the back of tooth from rubbing against the work. It is 4 to 7° for C.I. and 10 to 12 degrees for aluminium and brass.

(v) **Secondary clearance angle.** This angle is generally ground back of the land to keep the width of land within proper limits. It is usually 3 degrees greater than primary clearance angle.

(vi) **Land.** It is the narrow surface back of the cutting edge resulting from providing a clearance angle.

(vii) **Face.** Tooth face is the surface upon which the chip is formed when the cutter is cutting. It may be flat or curved.

(viii) **Back of tooth.** It is created by the gullet and secondary clearance angle.

A milling cutter is a multiple tooth tool and therefore higher requirements are made to its construction, sharpening and operation. The cutter should be rigidly and rigidly fixed on the spindle. The machine in which high velocity milling is to be done should not only be capable of operating at high speeds and feeds but possess ample rigidity.

### 1.32. Milling Cutter Sharpening

Milling cutters are usually sharpened on universal tool and cutter grinder. During grinding the cutter should be so set that the tooth can be advanced to the grinding wheel. Grinding is done with the face of a cup wheel. The cutter tooth should be positioned in respect to the wheel so that required relief angle ( $\gamma$ ) is obtained. The tooth face bears on a stationary tooth rest. Fig. 1.52 shows sharpening a face milling cutting by grinding the tooth flanks. The amount of offset ( $S$ ) is determined by using the following relation.

$$S = \frac{2}{D} \sin \gamma$$

where  $D$  is the cutter diameter.




Fig. 1.52

### 1.33. Material for Milling Cutters

The common materials used for manufacturing milling cutters are as follows :

- (i) High carbon steel
- (ii) High speed steel
- (iii) Cemented carbides
- (iv) Stellite
- (v) Ceramics.

High carbon steel is not commonly used except for a few cutters used for small scale production. High speed steel containing 18% tungsten is quite

commonly used. Cemented carbides are very commonly used when milling cutters are to be run at higher speeds. Stellite is very useful material for milling cutters when particularly machining hard metals, forgings and castings. Tips made of ceramics are also used in milling cutters. Such cutters, because of their brittleness, are used for finishing operations and smaller cuts. They are commonly used to machine cast iron and bronze.

Cemented carbide tipped cutters have the following advantages

- (i) Their production capacity is high.
- (ii) They can produce surface finish of high quality.
- (iii) Hardened steels can be machined by them.
- (iv) Their use leads to reduction in machining cost.

### 1.34. Number of Teeth in a Cutter

Milling cutters may be coarse tooth *i.e.* cutters with a large pitch and a small number of teeth or fine tooth *i.e.* cutters with a small pitch and a large number of teeth. The teeth are stronger in cutters with a coarse pitch. Coarse tooth straight flute cutters do not operate smoothly. Fine tooth cutters remove chips of relatively less thickness and are commonly used for finishing operation whereas coarse tooth remove thicker chip, resulting in removal of more metal in each cut and are used for roughing milling operation various empirical formulas are used to determine number of teeth in a cutter. A typical formula for calculating the number of teeth suitable for a cutter is as follows :

$$Z = A \sqrt{D}$$

where  $Z$  = Number of teeth

$D$  = Diameter of cutter

$A$  = Constant.

It depends upon the construction of cutter and machining conditions. Values of  $A$  are given in Table 1.14.

Table 1.14

Type of cutter	$\theta$ (Helix angle)	$A$
Solid cutters		
(a) Fine tooth	15 to 20°	2
(b) Coarse tooth	Upto 30°	1
Inserted blade cutters		
(a) Fine tooth	20°	0.9
(b) Coarse tooth	45°	0.8

### 1.35. Cutting Speed and Feed for Milling Cutter

**Cutting Speed.** It is the distance travelled per minute by the cutting edges of the cutter. It is expressed in metre per minute.

The cutting speed for milling cutter is found in the same way as for turning and drilling.

Let,  $D$  = Diameter of cutter in mm.

$N$  = R.P.M. of cutter

$V$  = Cutting speed

$$= \frac{\pi DN}{1000} \text{ metre/minute}$$

The cutting speed should be as high as possible constant with economics cutter life, before it needs regrinding.

**Feed.** It is the rate at which the workpiece advances past the rotating cutter. Three types of feed are distinguished.

(a) Feed per tooth ( $f_1$ )

(b) Feed per cutter revolution ( $f_2$ ).

(c) Table feed per minute ( $f_3$ ).

These feeds are related by following equations.

Let  $T$  = Number of teeth on cutter

$N$  = R.P.M. of cutter

$f_1$  = feed per tooth in mm

$$f_2 = f_1 \times T$$

$$f_3 = f_2 \times N = f_1 \cdot T \cdot N \text{ mm/min.}$$

Table 1.15 shows feed per tooth possible with various types of milling cutters.

**Table 1.15. Feed for H.S.S. cutters**

Cutter	Feed per tooth (mm)
Form cutter	0.05 to 0.2
Slotting cutter	0.5 to 0.15
End mill	0.1 to 0.25
Face mill	0.1 to 0.5
Spiral mill	0.05 to 0.2

The average value of cutting speed in metre per minute for H.S.S. cutter and cemented carbide cutter are shown in Table 1.16.

**Table 1.16**

Material to be machined	Tool material	
	H.S.S.	Cemented carbide
Aluminium	180—240	400—450
Brass soft	45—55	140
Copper	45—55	140
Gray cast iron	18—24	60
Cast iron hard	10—12	45
Mild steel	18—25	60
Hard steel	10—12	30

For a multipoint cutting tool such as milling cutter the maximum feed per tooth is limited by the following factors :

(i) Cutting edge strength.

(ii) Rigidity and allowable deflection.

(iii) Surface finish required.

(iv) Tool chip space.

With increase in feed, the cutting force gets increased and this causes greater deflection between tool and work piece. Accuracy can not be maintained if deflection is large. Proper cutting fluid can permit higher feeds and increased speeds as well as attainment of better surface finish. Cutting fluid should be directed to the exact point where cutting is taking place.

For setting up the operating conditions for any multipoint cutting tool there are three important variable that can be adjusted. They are as follows :

(i) Cutting speed.

(ii) Feed per cutting edge.

(iii) Cutting fluid.

### 1.36. Power Required at the Cutter

The horse power (H.P.<sub>c</sub>) required at the cutter depends on the volume of metal to be removed by the cutter per minute and varies for different materials.

$$\text{H.P.}_c = \frac{Kfdb}{1,00,000}$$

where  $f$  = Feed in mm/min,  $d$  = Depth of cut in mm.

$b$  = Width of cut in mm.

$K$  = Constant varying according to the material being cut.

The values of  $K$  are shown in Table 1.17.

Table 1.17

Material to be cut	Constant (K)
Light alloy (Positive rake)	1.3
Copper (Positive rake)	2.6
Brass (Positive rake)	3.0
Cast iron (Positive rake)	3.0
Bronze (Positive rake)	5.0
Steel (Negative rake)	5.0
Low carbon	8.5
High carbon	8.5

H.P.<sub>m</sub> = Horse power at motor

$$= \frac{HP_c}{\eta}$$

The efficiency ( $\eta$ ) of various milling machines is shown in Table 1.18.

Table 1.18

H.P. of the machine	Efficiency (%)
3	40
5	48
10	52
15	52
20	60
25	65
30	70
40	75

1.37. Machining Time

The machining time for plain milling and face milling is calculated at follows.

(i) Plain Milling. Fig. 1.53 shows milling operation being carried out by using plain milling cutter.

- Let  $h$  = approach in mm.
- $l$  = Length of workpiece in mm.
- $s$  = Overrun of cutter in mm.
- $L$  = Total cutter travel in mm =  $h + l + s$
- $D$  = Diameter of cutter ;  $t$  = Depth of cut
- $f$  = Feed/rev. in mm. ;  $N$  = R.P.M.




Fig. 1.53

Then  $T$  = Machining time.

$$= \frac{L}{N \times f}$$

The approach  $h$  can be calculated as follows.

In triangle AOP

$$OP^2 = (OA)^2 + AP^2$$

$$\left(\frac{D}{2}\right)^2 = \left(\frac{D}{2} - t\right)^2 + h^2$$

$$h = \sqrt{t(D - t)}$$

(ii) Face milling. Fig. 1.54 shows milling operation being carried out by face milling cutter.




Fig. 1.54

$l$  = Length of workpiece in mm.

$h$  = Approach in mm. ;  $s$  = Overrun of cutter

$L = l + h + s$  ;  $f$  = Feed in mm/rev.

$N$  = R.P.M.

$$T = \frac{L}{f \cdot N}$$

The approach  $h$  is can be calculated as follows.

$H$  = Width of workpiece,  $D$  = Diameter of cutter

$$OP^2 = OA^2 + AP^2$$

$$\left(\frac{D}{2}\right)^2 = \left(\frac{D}{2} - h\right)^2 + \left(\frac{H}{2}\right)^2$$

$$h = \frac{1}{2} [D - \sqrt{D^2 - H^2}]$$

**1.37.1. Broaching Tool**

A broaching tool or a broach has a series of multiple teeth. The main elements of a broaching tool are shown in Fig. 1.55. The first teeth are designed to do the heaviest cutting and are called roughing teeth. Next teeth are semi-finishing teeth which are followed by finishing teeth. The finishing teeth carry out finishing operation Fig. 1.56 shows teeth details. The rake angle (face angle) of the tooth depends on the material to be cut and its hardness, toughness and ductility.




Fig. 1.55




Fig. 1.56

The values of face angle for different materials are as follows :

Material	Face angle (Degrees)
Aluminium	10
Brass	5-5
Cast iron	6-8
Steel (hard)	8-12
Steel (soft)	16-20

The land of tooth determines its strength. The pitch determines the length of cut and chip thickness which a broach can handle.

During broaching operation the broach is either pulled or pushed by the broaching machine past the surface of the workpiece. In doing so each tooth of broach takes a small cut through the metal surface. Most broaches are

made from 18-4-1 high speed steel, ground after hardening. Carbide broaches are used extensively in broaching cast iron.

**1.38. Improving Cutting Efficiency**

The cutting efficiency during machining can be improved by using following methods.

- (i) Reduction of tool-face friction.
- (ii) By reducing chip length by means of chip breakers.
- (iii) By improving surface finish of tool face by honing or chrome plating.
- (iv) By increasing cutting speeds.
- (v) Increased depth of cut increases cutting efficiency by a small amount.

**1.39. Power Distribution**

Out of total power supplied to the machine tool the power available at the cutter depends upon the type of machine tool. A typical power distribution for a milling machine and a lathe is as follows.

**Milling Machine**

Electrical power input	= 100%
Losses in motor	= 16%
Losses in spindle transmission	= 18%
Power to feed	= 21%
Power available at cutter	= 45%

**Lathe**

Electrical power input	= 100%
Losses in motor	= 11%
Losses in machine	= 18.5%
Power to feed	= 0.5%
Power available at tool	= 70%

**1.40. To Determine Power Rating of Electric Motor**

The required power of main drive is determined on the basis of useful power calculated for the most effective cutting conditions. In designing general purpose machine tools the useful power is calculated for the maximum cutting speeds and feeds.

$$N_m = \text{Required power rating of electric motor} = N + N_f$$

where  $N$  = Useful power

$N_f$  = Power lost in over coming friction

$\eta$  = Efficiency of main drive.

$$= \frac{N}{N_m}$$

The efficiency ( $\eta$ ) may range from 0.7 to 0.85 for machine tools with a rotary primary motion having a single motor drive.

#### 1.41. Cutting Tool Design

The design of a cutting tool means determination of all the dimensions and shapes of all the elements of a cutting tool by carrying out calculations and graphical construction. The cutting of metals with a single point cutting tool is fully applicable to any kind of cutting tool since all tools remove a certain layer of stock and impart the required shape, size and surface finish to the machined part. The cutting teeth of all cutting tools whatever may be their shapes and purpose resemble to the point of single point tool.

The common procedure carried out during the design of cutting tool consists of following calculations :

- (i) To determine forces acting on cutting surface of the tool.
- (ii) To find out optimum tool geometry.
- (iii) To select suitable material for making cutting elements of the tool.
- (iv) To find suitable shapes of cutting and mounting elements of tool and to determine the tolerance on the dimensions of cutting and mounting elements of tool depending on machining accuracy required on work piece.
- (v) To determine strength and rigidity of mounting and cutting elements to tool.
- (vi) To prepare a working drawing of tool.

#### 1.42. Friction between Chip and Tool

Friction between the chip and tool plays a significant role in cutting process. It should be as low as possible friction can be reduced in the following ways :

- (i) Improved tool finish and sharpness of the cutting edge.
- (ii) Use of low friction tool material.
- (iii) Improved tool geometry.
- (iv) Use of cutting fluids.
- (v) High sliding speeds.

#### 1.43. Friction in metal cutting

During metal cutting the mean co-efficient of friction between the chip and the tool can vary considerably and is affected by changes in cutting speed, rake angle etc. This variance of mean co-efficient of friction results from the very high normal pressures that exist at the chip-tool interface.

Metallic surfaces consist of numerous hills and valleys. When cutting tool and metallic surfaces come in contact, the contact is established at the summits of only a few irregularities in each surface as shown in Fig. 1.56 (a).




Fig. 1.56 (a)

When a normal load is applied, yielding occurs at the tips of the contacting asperities and the real area of contact increases until it is capable of supporting the applied load. Usually the real area of contact is only a small fraction of the apparent area of contact.

$$A_r = \frac{N}{\sigma_y} \quad \dots(1)$$

where  $A_r$  = Real area of contact  
 $N$  = Normal Force  
 $\sigma_y$  = Yield stress of softer metal.

The adhesion resulting from the intimate metallic contact of these asperities has been termed as welding process and when sliding takes place, a force is required for the continuous shearing of the welded junctions at the tips of these asperities. Frictional force is given by

$P$  = Frictional force

$$A_r = \frac{P}{f_s} \quad \dots(2)$$

where  $f_s$  = Shear strength of softer metal.

From equation (1) and equation (2), we get

$$\frac{N}{\sigma_y} = \frac{P}{f_s}$$

$$\mu = \frac{P}{N} = \frac{f_s}{\sigma_y}$$

where  $\mu$  = co-efficient of friction. This shows that co-efficient of friction is independent of the apparent contact area. Since ratio  $\frac{f_s}{\sigma_y}$  is nearly constant for a given metal therefore co-efficient of friction will also remain constant.

**Example 1.1.** Determine the spindle speed for a high steel drill 12 mm diameter cutting medium carbon steel at 28 m/min.

**Solution.**  $V = 28$  m/min

$D =$  Diameter of drill = 12 mm.

$N$  = R.P.M. of spindle

$$V = \frac{\pi DN}{1000}; 28 = \frac{\pi \cdot 12 \cdot N}{1000}$$

$N = 743$  R.P.M. Ans.

**Example 1.2.** Determine the machining time to drill a hole of 20 mm diameter in a workpiece 25 mm thick by a drill at a cutting speed of 30 metre/min with a feed of 0.2 mm/rev.

**Solution.**  $L$  = Length of axial travel of drill in mm  
= Thickness of workpiece + 0.3  $D$

where  $D$  = Hole diameter

$$L = 25 + 0.3 \times 20 = 25 + 6 = 31 \text{ mm}$$

$V$  = Cutting speed = 30 metre per min

$$V = \frac{\pi DN}{1000}; 30 = \frac{\pi \times 20 \times N}{1000}$$

$N = 477$  R.P.M.

$T$  = Machining time

$f$  = feed / rev = 0.2 mm/rev.

$$T = \frac{L}{N \times f} = \frac{31}{477 \times 0.2} \text{ minute}$$

$$= \frac{31}{477 \times 0.2} \times 60 = 19.5 \text{ seconds. Ans.}$$

**Example 1.3.** A 30 mm H.S.S. drill is used to drill a hole in a cast iron block 100 mm thick. Determine the time required to drill the hole if feed is 0.3 mm/rev. Assume an over travel of drill as 4 mm. The cutting speed is 20 metre/min.

**Solution.**  $D$  = diameter of drill = 30 mm

$$V = \text{cutting speed} = \frac{\pi DN}{1000} = 20$$

$$20 = \frac{\pi \cdot 30 \cdot N}{1000}$$

$N = 202$  R.P.M. ;  $h$  = approach

$$= 0.3 D \text{ (assume)} = 0.3 \times 30 = 9 \text{ mm}$$

$s$  = over-travel = 4 mm ;  $L$  = Total length

$$= h + s + \text{Thickness of work piece}$$

$$= 9 + 4 + 100 = 113 \text{ mm.}$$

$T$  = Machining Time

$$= \frac{L}{fN} = \frac{113}{0.3 \times 202} \text{ where } f = \text{feed}$$

$$= 1.85 \text{ minutes.}$$

**Example 1.4.** Calculate the power required to drill 20 mm diameter hole in mild steel at a feed of 0.25 mm/rev and at a drill speed 300 R.P.M. Determine also the volume of metal removed per unit of energy.

**Solution.**  $D$  = hole diameter = 20 mm

$f$  = feed = 0.25 mm/rev.

$N$  = 300 R.P.M.

$$T_1 = \text{Torque} = C \cdot f^{0.75} D^{1.8}$$

where,  $C$  = Constant = 0.36 for mild steel.

$$T_1 = 0.36 \times 0.25^{0.75} \times 20^{1.8} = 27.96 \text{ newton-m.}$$

$P$  = Power

$$= \frac{2\pi NT_1}{60,000} = \frac{2\pi \times 300 \times 27.96}{60,000}$$

$$= 0.879 \text{ kW.}$$

Volume of metal removed per minute

= Area of hole  $\times$  Feed  $\times$  Speed

$$= \frac{\pi}{4} \times 20^2 \times 0.25 \times 300$$

$$= 23550 \text{ mm}^3.$$

$$\text{Energy consumption} = \frac{23550}{879}$$

$$= 21 \text{ mm}^2/\text{watt minute. Ans.}$$

**Example 1.5.** (a) A carbide face milling cutter of 200 mm diameter is used to take one cut across the face of a block of aluminium which is 200 mm wide. The length of block is 450 mm. If a feed of 0.75 mm/rev is used how long will it take to machine one cut on the block. The total travel is 12 mm. The cutting speed is 320 meter/minute.

(b) Calculate the time taken if the diameter of cutter is 300 mm.

**Solution.**

(a)

$D$  = Diameter of cutter = 200 mm

$H$  = Width of block = 200 mm

$l$  = Length of block = 450 mm

$f$  = Feed = 0.75 mm/rev.

$s$  = Overrun of cutter = 12 mm.

As the diameter of cutter is equal to width of block, (Fig. 1.57).

$h$  = Approach

$$= \frac{D}{2} = \frac{200}{2} = 100 \text{ mm.}$$

$N$  = R.P.M. of cutter

$$V = \text{cutting speed} = \frac{\pi DN}{1000}$$




Fig. 1.57

$$320 = \pi \times \frac{200}{1000} \times N$$

$$N = 510 \text{ R.P.M.}$$

$$\text{Total length, } L = l + H + s = 450 + 100 + 12 = 562 \text{ mm.}$$

$$T = \text{machining time} = \frac{562}{0.75 \times 510}$$

$$= 1.45 \text{ minutes. Ans.}$$

$$(b) \quad D = \text{Diameter of cutter} = 300 \text{ mm.}$$

In this case the diameter of cutter is more than the width of block

$$\therefore h = \text{Approach} = \frac{1}{2} [D - \sqrt{D^2 - H^2}]$$

$$= \frac{1}{2} [300 - \sqrt{300^2 - 200^2}] = 38 \text{ mm.}$$

$$\therefore L = \text{Total length} = l + h + S = 450 + 38 + 12 = 500 \text{ mm.}$$

$$V = \frac{\pi DN}{1000}$$

$$320 = \frac{\pi \times 300 \times N}{1000}$$

$$N = 340$$

$$T = \text{Machining time}$$

$$T = \frac{L}{fN} = \frac{500}{0.75 \times 340}$$

$$= 1.97 \text{ minutes. Ans.}$$

**Example 1.6.** A carbide milling cutter 250 mm in diameter is used to cut a block of mild steel with a plain cutter. The block is 500 mm long. If the feed is 0.50 mm/rev and depth of cut is 1.2 mm determine the time required to take one cut. The over travel is 16 mm. The cutting speed is 80 metre per minute.

$$\text{Solution. } D = \text{Diameter of cutter} = 250 \text{ mm.}$$

$$f = \text{feed} = 3.5 \text{ mm/rev.}$$

$$l = \text{Length of block} = 500 \text{ mm.}$$

$$t = \text{Depth of cut} = 1.2 \text{ mm}$$

$$s = \text{Over travel} = 16 \text{ mm.}$$

$$V = \text{cutting speed} = 80 \text{ metre/minute}$$

$$N = \text{R.P.M.}$$

$$V = \frac{\pi DN}{1000}$$

$$80 = \frac{\pi \cdot 250 \cdot N}{1000}$$

$$N = 102 \text{ R.P.M.}$$

$$h = \text{Approach} = \sqrt{t(D-t)}$$

$$= \sqrt{1.2(250 - 1.2)} = 17.3 \text{ mm.}$$

$$L = \text{Total length} = l + h + s$$

$$= 500 + 17.8 + 16 = 533.3 \text{ mm.}$$

$$T = \text{Machining time}$$

$$= \frac{L}{f \cdot N} = \frac{533.3}{0.5 \times 102}$$

$$= 10.45 \text{ minutes. Ans.}$$

**Example 1.7.** Determine the horse power required to face mill a block of grey cast iron 125 mm wide, using a tungsten carbide cutter 150 mm in diameter and having eight tooth. The depth of cut is 3 mm and a chip thickness of 0.25 mm is to be used. The cutting speed is 60 m/min and the specific horse power required for cast iron is 0.03 H.P./cm<sup>3</sup>/min.

$$\text{Solution. } V = \text{cutting speed} = 60 \text{ m/min.}$$

$$\text{Now } V = \frac{\pi DN}{1000}$$

$$60 = \frac{\pi \times 150 \times N}{1000}$$

$$\text{where } D = \text{cutter diameter}$$

$$N = \text{R.P.M. of cutter}$$

$$\therefore N = 128$$

$$\text{Now } f_1 = \text{feed per tooth (chip thickness)}$$

$$= 0.25 \text{ mm.}$$

$$f_2 = \text{feed per cutter revolution}$$

$$= f_1 \times \text{Number of teeth}$$

$$= f_1 \times 8 = 0.25 \times 8$$

$$f_3 = \text{feed per minute} = f_2 \times N$$



$$= 0.25 \times 8 \times 128 \text{ mm/minute}$$

$$= 256 \text{ mm/minute} = 25.6 \text{ cm/minute.}$$

The metal removal rate ( $w$ )

$$w = \text{Width of workpiece} \times \text{Depth of cut} \times \text{feed per minute}$$

$$= 125 \times 0.3 \times 25.6 \text{ cm}^3/\text{minute}$$

$$= 96 \text{ cm}^3/\text{minute}$$

Horse power required

$$= 96 \times 0.03 = 2.88. \text{ Ans.}$$

**Example 1.8.** The feed of an 8-tooth face mill cutter is 0.325 mm per tooth at 200 R.P.M. The material cut is 300 BHN Steel.

If the depth of the cut is 3 mm and width is 100 mm calculate the following :

(a) B.P. at the cutter

(b) H.P. at the motor.

**Solution.**  $HP_c = \frac{K \cdot f \cdot d \cdot b}{10,0000}$

where  $K = \text{Constant} = 8.5$  (From table 1.11)

$$f = \text{Feed} = 0.325 \times 8 \times 200$$

$$= 520 \text{ mm/minute.}$$

$$d = \text{Depth of cut in mm}$$

$$= 3 \text{ mm}$$

$$b = \text{Width of cut} = 100 \text{ mm.}$$

$$HP_c = \frac{85 \times 520 \times 3 \times 100}{10^5} = 12.48. \text{ Ans.}$$

Let the efficiency of the machine be 50%

$$HP_m = \text{Horse power at the motor}$$

$$= \frac{HP_c}{0.5} = \frac{12.48}{0.5} = 25. \text{ Ans.}$$

**Example 1.9.** Determine the power required by a milling cutter to take a cut 100 mm wide  $\times$  3 mm deep at 75 mm/min feed for an alloy steel. If the cutter diameter is 100 mm and cutting speed is 15 meter/min, find the mean torque at the arbor.

**Solution.** The horse power required at the cutter is given by

$$HP_c = \frac{K \cdot f \cdot d \cdot b}{10,0000}$$

Now  $K = 8.5$  (From table 1.11).

$$f = 75 \text{ mm/min.}$$

$$a = 100 \text{ mm.}$$

$$d = 3 \text{ mm.}$$

$$HP_c = \frac{8.5 \times 75 \times 100 \times 3}{100,000} = 1.9.$$

Mean force at the periphery of the cutter,

$$F = \frac{HP_c}{V} \times 4500$$

where  $V = \text{cutting speed} = 15 \text{ metre/min.}$

$$F = \frac{1.9 \times 4500}{15} = 570 \text{ kg.}$$

Mean torque at the arbor.

$$T = F \times \text{Radius of cutter}$$

$$T = 570 \times \frac{50}{1000} = 28.5 \text{ kg-m. Ans.}$$

**Example 1.10.** During turning a mild steel component with a 0—10—7—7—8,—9—1.5 mm shaped orthogonal shaped tool a depth of cut of 1.8 mm is used. If feed is 0.18 mm/rev. and a chip thickness of 0.36 mm is obtained determine the following :

(a) Chip thickness ratio

(b) Shear angle.

**Solution.** (a)  $r = \text{Chip thickness ratio} = t_1/t_2$

where  $t_1 = \text{chip thickness before cutting}$   
 $= 0.18 \text{ mm.}$

$t_2 = \text{chip thickness after cutting}$   
 $= 0.36 \text{ mm.}$

$$r = \frac{0.18}{0.36} = 0.5$$

(b)  $\beta = \text{Shear angle}$

$\alpha = \text{Back rake angle} = 0^\circ$  (given)

$$\tan \beta = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

$$= \frac{0.5 \times \cos 0}{1 - 0.5 \sin 0} = \frac{0.5}{1} = 0.5$$

$$\beta = 26^\circ - 34'.$$

**Example 1.11.** Determine the power required for milling a mild steel workpiece with a cutter of 80 mm diameter having 9 teeth and rotating at 120 R.P.M. The workpiece has a width of 60 mm. Depth of cut is 4 mm and tooth load is 0.03 mm.

**Solution.**  $P$  = Power in kW/cm<sup>2</sup>/min. It is given by the following formula

$$P = \frac{C}{\left[ f \sqrt{\frac{d}{D}} \right]^n}$$

where  $f$  = feed per tooth  
 $C$  = Material constant  
 $d$  = Depth of cut in mm.

The values of  $C$  and  $n$  depend upon material to be cut. The values are as follows :

Mild Steel :  $C = 0.02$  to  $0.03$

$n = 0.28$

Bronze :  $C = 0.006 - 0.007$

$n = 0.4$

Now  $C = 0.02$  (say)

$$f = \text{Feed per tooth} = \frac{F}{T}$$

where  $F$  = Feed rate, mm/min.  
 $T$  = Number of teeth on cutter  
 $f = 0.03$  mm.  
 $d$  = Depth of cut = 4 mm  
 $D$  = Diameter of cutter = 80 mm  
 $n = 0.28$

$$P = \frac{0.02}{\left[ 0.03 \sqrt{\frac{4}{80}} \right]^{0.28}} = 0.245$$

$$P_1 = \text{Power in kW} \\ = P \times b.d.f.T.N$$

where  $b$  = width of workpiece = 6 cm  
 $N$  = R.P.M. = 120

$$P^1 = 0.245 \times 6 \times 0.4 \times 0.003 \times 9 \times 120 \\ = 1.9 \text{ kW.}$$

**Example 1.12.** Determine the power required to cut a brass bar on a lathe when the cutting speed is 18 metres per minute, feed is 0.06 mm per revolution and depth of cut is 0.058 cm. Assume that the power lost in friction is 30%.

**Solution.** H.P. = Total horse power required  
 $= P_1 + P_2$

where  $P_1$  = Power required for cutting action

$P_2$  = Power lost in friction

= 30% of  $P_1$

$$\therefore \text{H.P.} = 1.3 P_1$$

$$= \frac{1.3 \times K.d.f.V}{4500}$$

where  $K$  = constant = 12000 for brass

$d$  = depth of cut in cm.

= 0.058 cm. = 0.58 mm

$f$  = 0.06 mm per revolution

$V$  = cutting speed

= 18 metres per minute.

The value of  $K$  depends on material being machined. The values of  $K$  are as follows.

Metal to be cut	$K$
Aluminium	6700
Brass	12000
Cast iron	8600
Steel	11000

$$\text{H.P.} = \frac{1.3 \times 12000 \times 0.58 \times 0.06 \times 18}{4500} \\ = 2.17 \text{ Ans.}$$

**Example 1.13.** Estimate the power of electric motor for a drilling machine to drill a hole 15 mm diameter in cast iron (soft) work piece at 450 R.P.M. and 0.2 mm feed. The specific power is 0.03 kW and efficiency of motor is 80%.

**Solution.**  $D$  = Hole diameter

= 15 mm

$N$  = 450 R.P.M.

$f$  = feed = 0.2 mm/rev.

$S$  = specific power

= Power required to remove material of one cubic centimeter per minute

= 0.03 kW

$\eta$  = Efficiency of motor = 0.8

$V$  = volume of metal to be cut during drilling

$$= \frac{\pi}{4} D^2 \times f \times N$$

$$\begin{aligned}
 P_1 &= \text{Power required at the drill} \\
 &= V \times S = 15.9 \times 0.03 = 0.477 \text{ kW} \\
 P &= \text{Power of electric motor} \\
 &= \frac{0.477}{\eta} = \frac{0.477}{0.8} = 0.6 \text{ kW. Ans.}
 \end{aligned}$$

**Example 1.14.** A broach is used to cut a key way 8 mm wide, 5 mm deep in a boss 64 mm long. Determine

(a) cutting length of broach

(b) Number of teeth on broach.

**Solution.**  $L$  = Length to be broached in mm

$$= 64 \text{ mm}$$

$p$  = pitch

$$= 1.5 \sqrt{64} = 12 \text{ mm.}$$

$d$  = Depth of cut = 5 mm

$h$  = rise per tooth

$$= 0.0875 \text{ mm (Assume)}$$

$Z_1$  = Number of teeth

$$= \frac{d}{h} = \frac{5}{0.0875} = 57$$

$Z_2$  = Number of finishing teeth

$$= 13 \text{ (say)}$$

$Z$  = Total number of teeth

$$= Z_1 + Z_2 = 57 + 13 = 70.$$

$p_1$  = Pitch for finishing teeth

$$= \frac{p}{2} = \frac{12}{2} = 6 \text{ mm}$$

(The pitch for finishing teeth is usually half of that adopted for cutting teeth)

$L$  = Total effective length (cutting length) of broach

$$= L_1 + L_2$$

where  $L_1$  = length of roughing teeth

$L_2$  = length of finishing teeth

$$L = 57 \times p + 13 \times p_1$$

$$= 57 \times 12 + 13 \times 6$$

$$= 762 \text{ mm.}$$

### PROBLEMS

- 1.1. (a) What is metal cutting? Define chip removal and non-chip removal process. Give examples.
- (b) Discuss basic elements of metal cutting.
- 1.2. Explain orthogonal cutting and oblique cutting.

- 1.3. (a) How are tools classified? State three examples of each.
  - (b) Explain with the help of neat sketch the complete geometry of a single point cutting tool.
  - 1.4. (a) Define 'tool signature'.
  - (b) Explain each term of a tool designated as 8, 12, 10, 7, 0, 15, 1.5 mm.
  - 1.5. (a) What is chip formation?
  - (b) Name the different types of chips formed in metal cutting. Describe each type with the help of neat sketches.
- State the conditions which favour the production of each type.
- 1.6. (a) List the main requirements of cutting tool material.
  - (b) Name and explain the various materials used for cutting tools.
  - 1.7. Write short notes on the following :
    - (a) Chip breakers
    - (b) Advantages of negative rake angle
    - (c) Curling of chip
    - (d) Cutting speed
    - (e) Feed
    - (f) Depth of cut
    - (g) Throw-away tips.
  - 1.8. (a) What is chip reduction coefficient?
  - (b) What are the effects of cutting variable on the chip reduction coefficient.
  - 1.9. (a) What is a multipoint cutting tool?
  - (b) Sketch a twist drill and describe its various elements.
  - 1.10. (a) Make a neat sketch of a twist drill, showing various angles.
  - (b) Define the following angles of a twist drill.
    - (i) Rake angle
    - (ii) Lip clearance angle
    - (iii) Point angle
    - (iv) Chisel edge angle.
  - 1.11. Write short notes on the following :
    - (a) Cutting fluids for drilling
    - (b) Twist drill grinding
    - (c) Twist drill failure
    - (d) Drill specifications.
  - 1.12. Analyse the forces acting on a drill.
  - 1.13. What are the parameters which affect the drilling torque.
  - 1.14. What factors decide the cutting speed of a drill.
  - 1.15. (a) What is a milling cutter.
  - (b) Sketch and explain
    - (i) Up milling
    - (ii) Down milling.
  - 1.16. Sketch a plain milling cutter and explain the various elements of the cutter.
  - 1.17. Write short notes on the following :
    - (a) Milling cutter sharpening.
    - (b) Number of teeth on a cutter
    - (c) Cutting speed
    - (d) Coarse tooth and fine tooth milling cutters.
  - 1.18. Explain how to calculate machining time in
    - (a) Plain milling
    - (b) Face milling.

- 1.19. A stab milling operation is carried out with a 60 inch diameter inserted carbide tooth cutter having 10 teeth at a cutting speed of 400 feet/min and a feed of 40 inches per minute. If the depth of cut is 0.02 inch and width of cut is 4.5 inch and the following relation is assumed :

$$F = -32000 b.d^{0.8} f^{0.7}$$

where  $F$  = Tangential force on cutter  
 $d$  = Depth of cut in inch  
 $b$  = Width of cut in inch  
 $f$  = Feed in inches per tooth

determine the following :

- (a) Tangential force exerted by the cutter.
  - (b) Torque transmitted by the cutter.
  - (c) Total H.P. required at the drive end of milling machine at a mechanical efficiency of 7%.
  - (d) Specific H.P. required at the arbor.
- 1.20. Determine the depth of cut taken on a lathe while turning brass at a feed of 0.625 mm per revolution and cutting speed of 24 metre/min if 3 horse power is available and 20% of power is lost in friction.
- 1.21. Estimate the time required for a single cut in each of the following machining operations.
- (a) To turn 25 mm dia  $\times$  1.0 mm long with cutting speed 30 m/min and a feed of 0.25 mm/rev.
  - (b) To turn 3 mm deep recess in a 50 mm dia and shaft using a 6 mm wide form tool with a cutting speed of 12 m/min and a feed of 0.05 mm.
- 1.22. (a) State the characteristics of carbide tools.  
 (b) Describe the power distribution in a milling machine and a lathe.
- 1.23. Write short notes on the following :  
 (a) Requirements of cutting tool.  
 (b) Power required at milling cutter.
- 1.24. Write short notes on the following :  
 (a) Improving metal cutting efficiency.  
 (b) Power distribution in the following machines.  
 (i) Lathe (ii) Milling machine.
- 1.25. Discuss the design of a cutting tool.
- 1.26. Explain the following terms with reference to a plain milling cutter :  
 (i) Radial rake angle (ii) Lip angle  
 (iii) Relief angle (iv) First clearance angle  
 (v) Second clearance angle. (A.M.I.E. 1982)
- 1.27. Sketch a broaching tool and describe its construction.
- 1.28. Write short notes on the following :  
 (a) Friction between chip and tool.  
 (b) Power rating of electric motor.  
 (c) Improvement of cutting efficiency during machining.

## Mechanics of Metal Cutting

In any metal cutting process, considerable forces are involved and in order to design machine tool holders and work holders that will withstand these forces, it is important to establish the magnitude of these forces and the directions in which they act. According to Ernst and Merchant the chip is assumed to behave as a rigid, body held in equilibrium by the action of the forces transmitted across the chip tool interface and across the shear plane. A number of attempts have been made to study the mechanics of the cutting process starting with Mallock in 1881. The theory suggested by Ernst and Merchant and later developed by Merchant considers orthogonal cutting with a flow type having no built up edge. The mode of plastic deformation is considered to be one of simple shear across a plan extending from the tool cutting edge to the junction of the chip with the original work surface. Lee and Shaffer in 1949 obtained a solution to the problem of the mechanics of metal cutting by using the slip-line field theory which was developed for studying the stress distribution in a body undergoing plastic deformation in two dimensions.

### 2.1. Cutting Forces in Orthogonal Cutting

The forces acting on a single point cutting tool are of fundamental importance in the design and of cutting and machine tools. For a conventional turning process the force system is shown in Fig. 2.1. The resultant cutting force  $P$  represented by  $OA$  acting on the tool is considered to be as vector sum of three component cutting forces mutually at right angles.

(i) Feed force  $F_x$  acts in a horizontal plane but in the direction opposite to the feed.

(ii) Thrust force  $F_y$  acting in the direction perpendicular to the generated surface.

(iii) Cutting forces  $F_z$  in the direction of the main cutting motion.

The relationships between forces,  $F_x$ ,  $F_y$  and  $F_z$  depend upon the cutting variables, geometry of the tool point, the work material, tool wear etc.

$$R = \text{Resultant force} = \sqrt{F_x^2 + F_y^2 + F_z^2}$$




Fig. 2.1

This three dimensional force system can be reduced to a two dimensional force system if in the orthogonal plane  $M$  the forces are considered in such a way that the entire force system is contained in the considered state, when

$$R = \sqrt{F_z^2 + F_{xy}^2}$$

$$F_{xy} = \sqrt{F_x^2 + F_y^2}$$

For this  $\lambda = 0$  and  $F_{XY}$  is contained in orthogonal plane  $M$ . This system is then known as orthogonal system of first kind for which the conditions are as follows :

- (i)  $\lambda = 0$
- (ii)  $0 < \phi < 90$
- (iii) Chip flow deviations are small.

The various forces for the orthogonal system of first kind is shown in Fig. 2.2 (a).

where  $\phi$  = Principal cutting edge angle

$\lambda$  = Inclination angle.

In orthogonal system of first kind

$$F_x = F_{xy} \sin \phi$$

$$F_y = F_{xy} \cos \phi$$

There is other orthogonal system known as orthogonal system of second kind in which  $F_y$  is made zero by having  $\lambda = 0$  and  $\phi = 90^\circ$  when two dimensional force system is




Fig. 2.2 (a)

Fig. 2.2 (b)

$$R = \sqrt{F_z^2 + F_x^2}$$

$$F_{xy} = \sqrt{F_x^2 + F_y^2}$$

$$= \sqrt{F_x^2 + 0}$$

$$= F_x$$

$$F_{xy} = F_y$$

when  $\phi = 0$  and  $\lambda = 0$

Fig. 2.2 (b) shows two dimensional force system in plane  $M$  for orthogonal system of second kind.

In orthogonal system the tool shape is specified by the following terms stated in order.

- (i) Inclination angle.
- (ii) Orthogonal rake angle ( $\alpha$ ).
- (iii) Orthogonal clearance angle ( $\alpha_1$ ).
- (iv) Auxiliary orthogonal clearance angle.
- (v) Auxiliary cutting edge angle ( $\phi_1$ ).
- (vi) Principal cutting edge angle ( $\phi$ ).
- (vii) Nose radius in millimeters.

The chip may be considered as a separate body held in equilibrium by the various forces shown in Fig. 2.2.




Fig. 2.2

Force  $F_s$  acts along the shear plane and is the resistance to shear of the metal in forming the chip. Force  $F_n$  is normal to shear plane. This is a backing up force on the chip provided by the work piece.  $F$  is the resultant of  $F_s$  and  $F_n$ . Force  $P$  is the frictional resistance of the tool acting downward against the motion of chip as it moves along the tool face. The normal force  $N$  is normal to the tool face and is provided by the tool. The resultant of these two forces is  $F'$  and is the force exerted by the tool on the workpiece. The force  $F$  and  $F'$  are equal in magnitude, opposite in direction and collinear.

$$\vec{F} = \vec{F}_s + \vec{F}_n$$

$$F' = \vec{P} + \vec{N}$$

The relation between various forces have been worked out by Merchant with a large number of assumptions as follows :

- (i) The chip behaves as a free body in stable equilibrium under the action of two equal, opposite and collinear resultant forces.
- (ii) Continuous chip without built up edge is produced.
- (iii) The cutting velocity remains constant.
- (iv) The cutting tool has a sharp cutting edge and it does not make any flank contact with the workpiece.

Merchant suggested a compact and easiest way of representing the various forces inside a circle having the vector  $F$  as diameter. Fig. 2.3 shows Merchant circle diagram which is convenient to determine the relation between the various forces and angles. The circle has a diameter equal to  $F$  or  $F'$  passing through the tool point.

$\alpha$  = Rake angle of tool.

$\beta$  = Shear angle.

$\gamma$  = Friction angle of the tool face.




Fig. 2.3. Merchant circle diagram.

As the chip slides over the tool face under pressure therefore the kinetic coefficient of friction ( $\mu$ ) may be expressed as

$$\mu = \frac{P}{N} = \tan \gamma$$

The cutting force  $F_H$  and feed force  $F_V$  can be measured with a cutting tool dynamometer and then the other forces can be determined in terms of  $F_H$  and  $F_V$ . Shear angle  $\beta$  can be obtained from the equation.

$$\tan \beta = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

$$\text{Chip thickness ratio, } r = \frac{t_1}{t_2}$$

where  $t_1$  = Chip thickness before cutting

$t_2$  = Chip thickness after cutting

$P$  = Friction resistance  
 $= F_H \sin \alpha + F_V \cos \alpha$

$N$  = Normal force  
 $= F_H \cos \alpha - F_V \sin \alpha$ .

$$F = \sqrt{F_H^2 + F_V^2}$$

$F_H$  = Cutting force  
 $= F \cos (\gamma - \alpha)$

Also  $F_S = F \cos \theta$

$$\therefore F = \frac{F_S}{\cos \theta}$$

where  $\theta = \beta + \gamma - \alpha$

$$\therefore F_H = \frac{F_S \cdot \cos(\gamma - \alpha)}{\cos \theta}$$

$$= \frac{F_S \cos(\gamma - \alpha)}{\cos(\beta + \gamma - \alpha)}$$

$\mu$  = Coefficient of friction

$$= \tan \gamma = \frac{P}{N}$$

$$= \frac{F_H \sin \alpha + F_V \cos \alpha}{F_H \cos \alpha - F_V \sin \alpha}$$

$$= \frac{F_H \cdot \tan \alpha + F_V}{F_H - F_V \tan \alpha}$$

The relationships for  $F_S$  and  $F_n$  are as follows :

$$F_S = F_H \cos \beta - F_V \sin \beta.$$

$$F_n = F_V \cos \beta + F_H \sin \beta.$$

Cutting force depends on the following :

(i) Material to be cut

(a) Hardness of material

(b) Strength of material

(ii) depth of cut (iii) feed

(iv) Tool geometry.

## 2.2. Stress and Strain in the Chip

During machining the chips are produced due to the plastic deformation of the metal and are subjected to stress and strain.

Let

$F_S$  = Shearing force

$f_S$  = Shear stress in the shear plane.

$A_1$  = Cross sectional area of chip before cutting.

$A_2$  = Area of shear plane.

Now

$$f_S = \frac{F_S}{A_2}$$

$$A_2 = \frac{A_1}{\sin \beta}$$

$$\therefore f_S = \frac{F_S}{A_1} \sin \beta$$

$$= \frac{(F_H \cos \beta - F_V \sin \beta) \sin \beta}{A_1}$$

$$= \frac{F_H \cos \beta \sin \beta - F_V \sin^2 \beta}{A_1}$$

where  $A_1 = b_1 \cdot t_1$ .

and  $b_1$  and  $t_1$  indicate width and thickness of chip respectively (Fig. 2.4).




Fig. 2.4

## 2.3. Shear Strain

The chip is considered to be consisting of series of plate like elements of thickness  $\Delta y$  and displaced through a distance  $\Delta s$  relative to each other as shown in Fig. 2.5. Strain is defined as the deformation per unit length.

$$e = \text{Shear strain} = \frac{\Delta s}{\Delta y}$$




Fig. 2.5

Fig. 2.6 shows elements of chips in the strain state.

Now

$$e = \frac{\Delta s}{\Delta y} = \frac{AB}{CD}$$

$$= \frac{BD}{CD} + \frac{AB}{CD}$$

$$= \cot \beta + \tan(\beta - \alpha).$$

$$= \frac{1}{\tan \beta} + \frac{\tan \beta - \tan \alpha}{1 + \tan \beta \tan \alpha} \quad \dots(1)$$




Fig. 2.6

$$\begin{aligned}
 &= \frac{1 + \tan^2 \beta}{\tan \beta + \tan^2 \beta \tan \alpha} \\
 &= \frac{\sec^2 \beta}{\tan \beta (1 + \tan \beta \tan \alpha)} \\
 &= \frac{\cos \alpha}{\sin \beta \cdot \cos (\beta - \alpha)}
 \end{aligned}$$

2.3. (a) To prove that

$$e = \frac{K^2 - 2K \sin \alpha + 1}{K \cos \alpha}$$

We know from equation (1)

$$e = \cot \beta + \tan (\beta - \alpha)$$

$$\tan \beta = \frac{r \cos \alpha}{1 - r \sin \alpha} = \frac{\cos \alpha}{\frac{1}{r} - \sin \alpha}$$

$$= \frac{\cos \alpha}{K - \sin \alpha}$$

Now

$$e = \cot \beta + \tan (\beta + \alpha)$$

$$e = \frac{\cot \beta + \tan \beta - \tan \alpha}{1 + \tan \beta \cdot \tan \alpha}$$

Substitute the values of  $\tan \beta$

$$e = \frac{K - \sin \alpha}{\cos \alpha} + \frac{\frac{\cos \alpha}{K - \sin \alpha} - \tan \alpha}{1 + \frac{\cos \alpha}{K} \times \tan \alpha}$$

$$\begin{aligned}
 &= \frac{K - \sin \alpha}{\sin \alpha} + \frac{\cos \alpha - \tan \alpha \times (K - \sin \alpha)}{K - \sin \alpha + \cos \alpha \cdot \tan \alpha} \\
 &= \frac{K - \sin \alpha}{\cos \alpha} + \frac{\cos^2 \alpha - K \sin \alpha + \sin^2 \alpha}{K \sin \alpha} \\
 e &= \frac{K - \sin \alpha}{\cos \alpha} + \frac{1 - \sin \alpha \times K}{K \cos \alpha} \\
 &= \frac{K^2 - K \cdot \sin \alpha + 1 - K \sin \alpha}{K \cos \alpha} \\
 &= \frac{K^2 - 2K \sin \alpha + 1}{K \cos \alpha}
 \end{aligned}$$

where  $K$  = Chip reduction coefficient.

### 2.4. Work Done and Power Required

The work done and power required in metal cutting is calculated as follows.

Let  $V$  = Cutting speed (metre/minute)

$F_H$  = Cutting force (kg)

$W$  = Total work done in cutting

$$= F_H \times V \text{ kgm/min}$$

$W_1$  = Work done in shear.

$$= F_S \times V_S \text{ kg-m/min.}$$

where  $V_S$  = Velocity of the chip relative to work in metre minute.

$F_S$  = Shear force in kg.

$W_2$  = Work done in friction

$$= P \times V_C \text{ kgm/min}$$

where  $V_C$  = Velocity of the chip relative to the cutting tool in metre/min.

$$W = W_1 + W_2$$

$$F_H \times V = F_S \times V_S + P \times V_C.$$

$$\text{H.P.} = \frac{F_H \times V}{4500}.$$

### 2.5. Power Consumed in Metal Cutting

Specific power means power required to remove unit volume of metal.

During two dimensional metal cutting operation the total energy (power) consumed is found as follows :

$U$  = Total energy (power) consumed her unit time

$$= F_H \times V$$

where  $F_H$  = Cutting force (kg)

$V$  = Cutting speed (mpm)

$$P = \text{Power} = \frac{F_H \times V}{4500}$$



$$\begin{aligned}
 E &= \text{Energy consumed per unit volume} \\
 &= \frac{U}{V \cdot b \cdot t} \\
 &= \frac{F_H \times V}{V \cdot b \cdot t} \\
 &= \frac{F_H}{b \cdot t}
 \end{aligned}$$

where  $b$  = Width of cut  
 $t$  = Depth of cut

Energy consumed per unit volume is utilised as follows.

(i) Shear energy per unit volume ( $E_S$ ) on shear plane

$$\begin{aligned}
 E_S &= \frac{F_S \cdot V_S}{V \cdot b \cdot t} \\
 &= f_S \left[ \frac{V_S}{V \sin \beta} \right]
 \end{aligned}$$

where  $F_S$  = Shear force.

$V_S$  = Shear velocity

$f_S$  = Shear stress

$\beta$  = Shear angle

(ii) Friction energy per unit volume ( $E_f$ ) on the tool face.

$$E_f = \frac{F \cdot V_C}{V \cdot b \cdot t}$$

where  $F$  = Force along tool face.

$V_C$  = Chip velocity.

(iii) Surface energy per unit volume ( $E_A$ ) due to the formation of new surface area in cutting.

(iv) Momentum energy per unit volume ( $E_m$ ) due to the momentum change associated with the metal as it crosses the shear plane

$$E_m = \rho V^2 e^2 \sin^2 \beta$$

where  $\rho$  = Mass density of metal

$e$  = Shear strain

It is observed that the surface energy per unit volume ( $E_A$ ) and momentum energy per unit volume ( $E_m$ ) are relatively very small and can be neglected and therefore to a good approximation, we have

$$E = E_S + E_f$$

In general the friction energy is found to be about  $\frac{1}{3}$  the shear energy in turning.

It is important to reduce coefficient of friction between tool and chip in metal cutting because when the coefficient of friction is decreased in metal

cutting not only a decrease in friction work will result but a decrease in the shear work as well.

## 2.6. Machine Tool Efficiency

H.P. used in metal cutting is estimated by measuring the gross horse power ( $HP_g$ ) and  $t$  are horse power ( $HP_t$ ).

$$\text{H.P. cutting } (HP_c) = HP_g - HP_t$$

$\eta$  = Machine tool efficiency

$$= \frac{HP_c}{HP_g}$$

## 2.7. Metal Removal Rate ( $w$ )

It is the volume of metal removed in unit time. It helps to calculate time required to remove specified quantity of material from the workpiece.

Let,

$t$  = Depth of cut in centimetres

$f$  = Feed/revolution in cm.

$V$  = Cutting speed in cm/minute.

$w = t \cdot f \cdot v \text{ cm}^3/\text{min.}$

The metal should be removed by the cutting rapidly to reduce the machining cost. To achieve this the following factors should be considered.

(i) The cutting tool should be made up of proper material.

(ii) The cutting tool should be properly ground.

(iii) Tool should be held rigidly and there should be no vibrations.

(iv) Depending upon the rigidity of the machine maximum speed and feed should be used.

## 2.8. Ernst-Merchant Theory

According to this theory the relation between rake angle  $\alpha$ , shear angle  $\beta$  and friction angle  $\gamma$  is as follows.

$$\beta = \frac{\pi}{4} - \frac{\gamma}{2} + \frac{\alpha}{2}$$

(i) Shear will take place in a direction in which energy required for shearing is minimum.

(ii) Shear stress is maximum at the shear plane and it remains constant.

We have proved that

$$F_H = \frac{F_S \cdot \cos(\gamma - \alpha)}{\cos(\beta + \gamma - \alpha)}$$

Now

$$F_S = f_S \cdot A_2$$

where  $f_S$  = Shear stress

$A_2$  = Area of shear plane

$$= \frac{b_1 t_1}{\sin \beta}$$

$$\therefore F_H = f_s \cdot \frac{b_1 t_1}{\sin \beta} \frac{\cos(\gamma - \alpha)}{\cos(\beta + \gamma - \alpha)}$$

Differentiating w.r.t.  $\beta$ .

$$\frac{dF_H}{d\beta} = -f_s \cdot b_1 t_1 \cos(\gamma - \alpha) \times \left[ \frac{\cos \beta \cdot \cos(\beta + \gamma - \alpha) - \sin \beta \sin(\beta + \gamma - \alpha)}{\sin^2 \beta \cos^2(\beta + \gamma - \alpha)} \right]$$

= 0 in order that  $\beta$  will assume that value which required a minimum force to cut the material.

$$\therefore \cos \beta \cos(\beta + \gamma - \alpha) - \sin \beta \sin(\beta + \gamma - \alpha) = 0$$

$$\cos(\beta + \beta + \gamma - \alpha) = 0$$

$$\cos(2\beta + \gamma - \alpha) = 0$$

$$2\beta + \gamma - \alpha = \frac{\pi}{2}$$

$$\beta = \frac{\pi}{4} - \frac{\gamma}{2} + \frac{\alpha}{2}$$

### 2.9. Lee and Shaffer's Theory

The theory of Lee and Shaffer was the result of an attempt to apply the plasticity theory to the problem of orthogonal metal cutting. The assumptions made in this theory are follows :

- (i) The work material ahead of the tool behaves as ideal plastic mass.
- (ii) There exists a shear plane which separates the chip and workpiece.
- (iii) No hardening in chip occurs. On the basis of above assumptions the following relationship was obtained.

$$\beta + \gamma - \alpha = \frac{\pi}{4}$$

Lee and Shaffer realised that the above equation could not apply for all values of  $\gamma$  and  $\alpha$  such as when  $\gamma$  in  $\frac{\pi}{4}$  and  $\alpha$  is zero this will give  $\beta$  as zero.

Therefore they modified the above equation by including the effect of built up edge by using addition angle  $\theta$  depending on the size of built up edge and arrived at the following solution.

$$\beta + \gamma - \alpha - \theta = \frac{\pi}{4}$$

### 2.10. Velocities in metal cutting

There are three velocities in a metal cutting process :

- (i) **Cutting velocity (V).** It is the velocity of the tool relative to the workpiece and directed parallel to the cutting force.

- (ii) **Chip velocity ( $V_C$ ).** It is the velocity of the chip relative to the tool and is directed along the tool face.

- (iii) **Shear velocity ( $V_S$ ).** It is the velocity of the chip relative to the workpiece and is directed along the shear plane.

#### 2.10.1. Velocity Relationship

The velocity relationship in orthogonal cutting are shown in Fig. 2.7. The various velocities are the cutting velocity  $V$ , chip velocity  $V_C$  and shear velocity  $V_S$ . Velocity  $V_C$  is the velocity of chip relative to tool and is directed along tool face and  $V_S$  is velocity of chip relative to workpiece and is directed along shear plane (Fig. 2.8).




Fig. 2.7




Fig. 2.8

In Fig. 2.8, from right angle triangle  $OCA$

$$AC = OA \sin \beta$$

$$AC = V \sin \beta$$